2420 Invoice: Tri-State Heavy Repair LLC 7130793 3/12/2024 Date: 889 U.S. 6 Port Jervis, NY 12771 service@nysheavyrepair.com (845) 856-0900 Remit Payment To Bill To Tri-State Heavy Repair LLC TROVE 889 U.S. 6 Port Jervis, NY 12771 Unit# Service Writer Customer PO Due Date Authorizer Terms Service Order Ciano, Frank ART 3/12/2024 COD 3293 Quantity Rate Amount Description Item Complaint: UNIT TOWED IN FOR NO START NO CHARGE Cause: UNIT TOWED IN FOR NO START NO CHARGE \$0.00 Chassis / Chassis / UNIT TOWED IN FOR NO START NO 0.00000 Labor CHARGE - Completed: 12/11/2023 \$0.00 Subtotal Complaint: DIAGNOSED AND FOUND UNITS FUEL PUMP NOT OPERATING. REMOVED FUEL PUMP INSTALLED NEW. AT TIME OF INSTALLATION WHEN WE WENT TO TEST FOUND THAT AIR WAS GETTING INTO SYSTEM CAUSING THE PUMP TO BURN OUT. TRACED BOTH FUEL LINES FOUND CRACKED LINE REPAIRED TESTED OK Cause: Customer request (Inspection) Chassis / Chassis / DIAGNOSED AND FOUND UNITS FUEL 17.00000 \$105.00 \$1,785.00 Labor PUMP NOT OPERATING. REMOVED FUEL PUMP INSTALLED NEW. AT TIME OF INSTALLATION WHEN WE WENT TO TEST FOUND THAT AIR WAS GETTING INTO SYSTEM CAUSING THE PUMP TO BURN OUT. TRACED BOTH FUEL LINES FOUND CRACKED LINE REPAIRED TESTED OK - Completed: 12/11/2023

\$132.68

\$47.85

\$4.4225

\$2,3925

30.00000

20.00000

Diesel Delivery - Diesel Delivery

NYLONE TUBE - 3571312C1

Parts

Parts

Description	Qı	uantity	Rate	Amount
. comment with residence	2	.00000	\$52.1275	\$104.26
_	1	.00000	\$46.1825	\$46.18
_			\$59.3485	\$178.05
_			·	\$965.31
				\$80.75
000 000 0000 000000 000000 000	K - 333442731VX			\$56.62
	301(-333427014)			\$747.23
FILTER FUEL HOUS	11/0 - 000000001			\$114.72
VNTILATR - 3587712			0.4 0.530, 22 - 03	
ACTUATOR - 43074	I1RX	1.00000	36 35 35 35 35 3	\$493.64
	Fitting - 3559213C2 Fitting - 3578152C1 Fitting - 3559214C1 FUEL PUMP - 369076 CAM SHAFT SENSO CRANK SHAFT SEN FILTER FUEL HOUS VNTILATR - 3587712	Fitting - 3559213C2 Fitting - 3578152C1 Fitting - 3559214C1 FUEL PUMP - 3690768 CAM SHAFT SENSOR - 55944275NX CRANK SHAFT SENSOR - 5594276NX FILTER FUEL HOUSING - 3990080C1 VNTILATR - 3587712C1 ACTUATOR - 4307411RX	Fitting - 3559213C2 Fitting - 3578152C1 Fitting - 3559214C1 FUEL PUMP - 3690768 CAM SHAFT SENSOR - 55944275NX CRANK SHAFT SENSOR - 5594276NX FILTER FUEL HOUSING - 3990080C1 VNTILATR - 3587712C1 ACTUATOR - 4307411RX 1.00000	Fitting - 3559213C2 2.00000 \$52.1275 Fitting - 3578152C1 1.00000 \$46.1825 Fitting - 3559214C1 3.00000 \$59.3485 FUEL PUMP - 3690768 1.00000 \$965.3085 CAM SHAFT SENSOR - 55944275NX 1.00000 \$80.7505 CRANK SHAFT SENSOR - 5594276NX 1.00000 \$56.6225 FILTER FUEL HOUSING - 3990080C1 1.00000 \$747.2285 VNTILATR - 3587712C1 1.00000 \$114.724

Complaint: CUSTOMER PICKED UNIT UP, UNIT RAN AND THEN BEGAN TO REPEAT THE INITIAL COMPLAINT TOWED BACK TO SHOP.

Cause: Customer request

(Inspection)

Chassis / Chassis / CUSTOMER PICKED UNIT UP, UNIT 0.00000 Labor

RAN AND THEN BEGAN TO REPEAT THE INITIAL

COMPLAINT TOWED BACK TO SHOP. - Completed:

2/26/2024

Subtotal \$0.00

Complaint: TOWED UNIT TO ARKEL NO CHARGE

Cause: Customer request

(Inspection)

Chassis / Chassis / TOWED UNIT TO ARKEL NO CHARGE - 0.00000 Labor

\$0.00

\$0.00

Completed: 2/26/2024

Subtotal

\$0.00

Complaint: ARKEL DIAGS AND FINDS ANOTHER FILTER CLOGGED REPLACED STILL HAVING THE SAME ISSUE. ARKEL REPLACES ECM WITHOUT CONSENT UNIT STILL HAS ISSUE. MADE THEM REPLACE TO OLD ECM AND TOWED BACK TO SHOP

Cause: Customer request

(Inspection)

Item	Description	Quantity	Rate	Amount
Labor	Chassis / Chassis / ARKEL DIAGS AND FINDS ANOTHER FILTER CLOGGED REPLACED STILL HAVING THE SAME ISSUE. ARKEL REPLACES ECM WITHOUT CONSENT UNIT STILL HAS ISSUE. MADE THEM REPLACE TO OLD ECM AND TOWED BACK TO SHOP - Completed: 2/26/2024	0.00000		\$0.00
Parts	SUBLET BILL ARKEL - ARKEL		\$2,450.36	\$2,450.36
				\$2,450.36
	and the second s	45 - 15 - 16 - 17 - 18 - 18 - 18 - 18 - 18 - 18 - 18		an property of the control of the co

Complaint: CUSTOMER SUPPLIED TURBO REPLACED ADDED OLD VGT

ONTO UNIT TEST DROVE OK ENGINE LIGHT WILL NOT GO OFF

Cause: Customer request

(Inspection)

Labor Chassis / Chassis / CUSTOMER SUPPLIED TURBO

REPLACED ADDED OLD VGT ONTO UNIT TEST DROVE

OK ENGINE LIGHT WILL NOT GO OFF - Completed:

2/26/2024

Subtotal \$682.50

\$105.00

6.50000

\$682.50

Unit: 1 VIN: 3HSDZAPR3JN448914

2018 International LT625

Chassis: 1 Miles

Labor \$2,467.50

Parts \$5,417.65

Pre-Charge Subtotal \$7,885.15

Exempt

(0% of \$7,885.15)

\$0.00

Total \$7,885.15

Payments & Credits

\$0.00

Balance Due \$7,885.15

Any warranties on the parts and accessories sold hereby are made by the manufacturer. You understand and agree that we make no warranties of any kind unless expressed in writing. You hereby authorize us to perform the repair work herein set forth and to purchase the necessary material and parts to perform such repair work. You agree that we are not responsible for loss or damage to your vehicle or articles left in your vehicle in case of fire, theft, or any other cause beyond our control or for any delays caused by unavailability of parts or delays in part shipments by the supplier or transporter. In addition, you agree that we are not responsible for damages to your vehicle from freezing due to lack of antifreeze. You hereby grant our employees permission to operate your vehicle on streets, highways, or elsewhere for the purpose

of testing and/or inspection. You acknowledge and agree that an express mechanic's lien on your vehicle is granted to secure payment of this invoice for the repair work					
detailed in this invoice.					
Customer Signature:					
Printed Name:	Date:				

4/4