

Date	Miles	Hours	Description	Parts
3/28/16	336514	20061	Change oil and filters	2, 1791XE Filters 11 Gals 15W40 2798 Filter
			Replace the air filter	
			Grease body and chassis	
			Reinstall the left front spring pin	
			Replace the rear rear axle brakes	2, XK3124707QP Brake kits
			Tighten the driveshaft yoke	
			Replace the windshield wiper blades	2, 06-018 Wiper blades
			Replace the cab's right air bag	227QS348 Air bag
			Safety inspection	
4/6/16	336860	20081	Replace one pigtail	2 Wire pigtail 2, Butt connectors
4/15/16	337009	20097	Replace the fuel filter	3587 Filter 3588 Filter
4/19/16	337009	20097	Replace the rear hoist hoses	2, 34x24", 16MJIC, 16XFJIC Hoses
			Adjust clutch	
5/11/16			Towed in from Freehold to Allied, motor	
6/4/16	337359	20124	Back from Allied	
6/18/16	339092		Replug the tail light wire to the headlight switch	
6/25/16	339901	20260	Replace the clutch brake	SCB200 Clutch brake
			Bring back to Allied, engine running rough	
6/28/16			Pick up from Allied	
6/30/16	340121		Repair the left front turn single wire	
7/12/16	341334	20343	Towed in from Manchester, air compressor	
			Replace the air compressor and it's cooling hose	S9111530557 Compressor 1/2 x 1', 8XSAE XF Hose
9/2/16			Road call, Lakewood, blown hoses, Pull off hoses, have them made at Van Sant	3/4x3, 16FJIC 3/4x7, 12FJIC 12FJIC 45
9/3/16	347848	20683	Change oil and filters	2, 1791XE Filters 7703 Filter 11 Gals 15W40
			Replace the fuel filter	3587 Filter 3588 Filter
			Grease body and chassis	
9/7/16	348223		Replace the right rear rear wheel seal and outer bearing	370031A Seal SET426 Bearing kit 1/2 Gal Gear lube
11/12/16	355960	21112	Change oil and filters	2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter
			Replace the fuel filter	
			Blow out the air filter	
			Grease body and chassis	
			Replace two batteries	2, used batteries
			Emission test	
			Clean and lube outside hoist controls, replace the boots	2, M-G-A3760 Boots
12/17/16	3600065		Grease body	
12/28/16	3600881	21374	Repair the rear marker	1156 Bulb
1/12/17	362440		Repair the right front turn single	4, Butt connectors
			Replace the bulb, repair wires	4805AAY4 Lamp
1/18/17	363352		Replace the right front turn single	2, Butt connectors
			Weld the mud flap bracket back on	2, 21939298 Filters
2/4/17	365452	21611	Change oil and filters	7703 Filter 3587 Filter 3588 Filter 2798 Filter
			Replace the fuel filter	
			Replace the air filter	
			Grease body and chassis	
2/7/17			To Allied, engine miss, miss cleared up, can not find anything	

Date	Miles	Hours	Description	Parts
2/10/17			Pull the right rear spring, sent to R&H for rebuilding Replace the broken left rear body roller	Rebuilt spring M-G-521-AO Roller M-G-2185W Pin M-G-552-W Washer M-G-1525 Cotter pin
2/15/17	365827	21633	Replace the spring pads	2, 25121508 Pads 2, 12014 Pads XK3124707QP Brakes kit
3/1/17			Replace the right forward axle brakes Safety inspection Tighten the right mirror Clean batteries Weld the right stack bracket and the exhaust y-pipe Grease body and chassis	
4/12/17	366662	21694	Smoke test	
5/24/17	367019	21720	Replace the AC clutch Vacuum down and recharge the A/C system	46399931 Clutch
6/12/17	367306	21742	Unjamed the right short stop, Heat and grinding	
6/17/17	367437	21752	Straighten out the right front axle, Replace the spacer pin, Repair the spacer Tighten the center bolt, and U-bolts	MMCK48 Pin
6/24/17	367692	21777	Fish out a rag from the fuel tank Replace the cap	25195379 Cap 3050 Lamp
6/27/17	367811		Replace a rear bumper marker	
7/4/17	368302		Adjust brakes	
7/8/17	368647		Clean out the AC drain	
7/22/17	370395		Clean out the AC evaporator Replace the flasher	EL12 Flasher
7/29/17	370424	21992	Replace the left front turn single lamp	4805AAY4 Lamp
8/12/17	371579	22079	Replace the headliner trim Replace the radio Replace the hydraulic filter & the tank's breather Grease body Place a winch bar in the cab Replace the city horn	25171344 Trim 5165-CQCX160U5A Radio 1108713 Filter 1348 Filter 1903060 Bar 20766981 Horn
8/15/17	371743	22089	Adjust brakes	
8/17/17	371978		Replace the left front hub cap Replace a missing door latch screw Replace the low air warning bulb	1643 Hub cap 130AX84 Screw # 37 Bulb
8/19/17	372150	22121	Repair the revers lights	Fuse holder 20A Fuse 2, Wire ends
9/1/17	373042		Cut off the control valve bracket, weld a new tank top, reattach the bracket Replace the O-ring in the return filter housing	183 O-ring
9/8/17	373373		Replace the accelerator pedal	25174960 Pedal
9/11/17	373595		Replace the left fender spot mirror	207-6 Mirror
9/13/17	373898		Adjust brakes	
9/19/17	374408		Replace the parking knob	108235N Knob
9/22/17	374585		Replace the outside control brackets	M-G-A3640 Control brackets
10/3/17	375419		Adjust brakes Tighten up the adjustable steering wheel lock	
10/4/17	375562		Replace both rear hold down straps	
10/7/17	375902	22422	Change oil and filters Replace the fuel filter Replace the air filter Replace the surge tube Replace six side rollers	2, M-G-A3306 Strap 2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter 2798 Filter 25089930 Tube M-G-521-AO Roller

Date	Miles	Hours	Description	Parts
10/11/17	376135	22444	Replace the power steering return hose	4 Ft of 8-1-10 Hose 2, #12 clamps 2 Gals 15W40 2, AM82F004 Springs 25624526 Latch 62QS3238 Control
10/13/17	376234		Replace the springs on the ICC bar	
10/14/17	376354	22459	Replace the left door latch and the inside latch control	
10/18/17	376538		Open up the heater control valve Add a bracket to the valve to support it	
10/21/17	376896		Adjust the toe Adjust brakes	95943 Clip
10/28/17	377432	22545	Replace the broken headlight adjuster clip Weld up the tool box	2, XK3124715QP Brake kits 2, 65152B Drums 40010011 Slack adjuster 296962N Pin 561 Bulb
11/4/17	378034		Replace the front brakes and drums Replace the left front slack adjuster	
11/7/17	378354		Replace the parking brake knob pin	
11/11/17	378670		Replace the missing dome light bulb Tighten up the bulb's anchor	25190654 Thermocouple 6, #37 Bulbs 296962N Pin
11/17/17	378928		Replace the thermocouple	
11/18/17	378998	22660	Replace six indicator bulbs	
1/29/18	379554		Replace the parking brake knob pin Adjust brakes	Auto tarper kit
3/16/18			Install a auto tarper Replace the right forward axle brakes and drum	XK3124707QP Brakes kit 3600AX Drum 40010144M1D Slack adjuster M-G-6525BO Hold down M-G-6526BO Hold down
4/7/18	383683	22986	Replace the right rear rear slack adjuster Install the ratchet handle style hold downs	
4/14/18	384290		Grease body	
4/28/18	385125	23095	Replace the horn roller contact Change oil and filters	344SL13 Contact 2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter
5/5/18	385690	23137	Replace the fuel filter Blow out the air filter Grease body and chassis Emission test	
5/12/18	386335		Grease body	
6/1/18	387330	23257	check pressure, OK Fill the hydraulic tank Adjust clutch, replace the missing bolt on the lock R&R the right lift cylinder, bypassing	Rebuilt cylinder 2" Pipe 708515 Mirror 313GC5230MX Pump
6/8/18			Replace the tool box mount Replace the right spot mirror	
8/4/18			Replace the right spot mirror	
8/23/18	389142	23392	Replace #5 EUP Clean Battery cables Clean plugs in the wire harness. eeuc, veuc Replace the lift pump Replace the auto tarp pivots mount Replace the cable	322GC45 Pump 2, 3X7 x 5 CB7/8X78B Cable
11/13/18	393102		Tighten the right side mirror Repair a air leak along the frame	3' of 1/2" Synflex 1/2" Union 4, #37 Bulbs 2, 6-018-1 Blades
12/14/18	393784		Replace 4 burnt out indicators bulbs Replace the windshield wiper blades Safety inspection Adjust clutch Replace the 1st tongue rod Replace the rear side torque rod Weld up the hoist frame on the left side	25170833 Rod 25162529 Rod
1/8/19	359051		Repair a brake air line Repair the hoist up air line Adjust brakes	2, 3/8 Unions 1/4 Union
1/19/19	396022			
1/21/19	396100			
1/22/19	396232			

Brake type des

Brake Type
DesignationB
B
BW
D
D
1
2
H
SL
R

Date	Miles	Hours	Description	Parts
1/28/19	396573	23905	Replace the foot valve, relay valve and the spring brake valve	103010N Relay valve 286364N Spring brake valve 286171N Foot valve
			Replace the right reeving cylinder with its block and hoses	2316W Shive block M-G-A3147 Cylinder 3/4x13, 12MP, 12 O-ring Hose 3/4x24, 12MP, 12 O-ring Hose
2/9/19	397214	23981	Change oil and filters	2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter 2798 Filter
			Replace the fuel filter	
			Replace the air filter	
			Grease body and chassis	
			Check lights	
			Replace the slight gage	3406 Gage
2/19/19	397868		Air blowing though the relay valve, replace	103010N Relay valve
			Adjust brakes	
2/28/19	398425		Adjust brakes	
3/14/19	399586		Replace the support bar above the right battery box	85150882 Support
3/19/19	400178		Replace the bracket on the control valve	Spot mirror bracket
4/3/19	401488		Reattach the right rear of the fender	
4/15/19	402587	24385	Repair the left taper work light wires	
4/22/19	403203		Repair a air leak in the hoist control	2, 15A Mini fuse 1/4 Union
5/4/19	404306	24507	Grease body and chassis	
5/20/19	405400		Make up and weld in a cable hook	
5/30/19	405908	24624	Replace the right rear spring, from 40	
			Replace the saddle and the U-bolts	
6/1/19	406090		Replace the rear rear brakes, seal & inner bearing and race	
6/19/19	407671		Grease body and chassis	
			Replace the right rear rear brakes and seal	XK3124707QP Brake kit 370031A Seal
6/24/19	407923	24759	Replace the right 1st rear axle slack adjuster	XK3124707QP Brakes kit 40010144M1D Slack adjuster
			Replace the left 1st rear brakes	
6/28/19	408284		Oil leak at the air compressor, tighten the compressor bolts	
			Check oil add 2.5 Gals.	
7/4/19	408733	24821	Change oil and filters	2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter 2798 Filter 4, 8609-524 Nuts
			Replace the fuel filter	
			Replace the air filter and it's cover nuts	
			Adjust brakes	
			Replace the air compressor front cooling hose	
7/20/19	409829		Easy out and replace a broken fitting in the water pump	3/8x3', 3/8MP Hose
			Cut out, make and weld in a new left rear light panel	
7/29/19	410174		Replace the broken left headlight adjuster clip	4" Grommet 2" Grommet 7313-95943 Clip
			Weld the crack at the Y-pipe	
			Replace the exhaust, turbo to y-pipe	25122768 Pipe 4' of 4" Flex pipe 25165770 Pipe 41989 Pipe adapter FL5SS Clamp 2' X007824 Clamps 26361Y Lamp
			Replace a cab marker lamp	
			Weld plate at the hoist ends	
			Straighten up the toolbox	
8/8/19	411148		Replace the front Jake brake solenoid	
			Adjust clutch	
8/10/19	411370	25024	Replace the left tail light and its pigtail	20906444 Solenoid
			Grease body	4050 Lamp 94902 Pigtail
9/13/19	414181		Replace the valve mounting bracket	3, Butt connectors L Bracket

Date	Miles	Hours	Description	Parts
10/3/19	415289		Repair a wire to the back up lights	2, M-G-A3306 Straps
10/5/19	415377		Replace both hold down straps	
10/26/19	416967		R & R the fuel tank to weld the stack support	
			Weld the Y pipe	62-707L pivot pin
11/6/19	417534	25432	Replace the tarps left pivot pin	62-702 Arm
			Replace the bottom arm	
11/9/19			Road call, Neptune City, PTO stop, replace the fuse with a	20A Breaker
			Circuit breaker	
11/11/19	417892		Locate and repair the short in the PTO wire	2, 21939298 Filters
11/18/19	418249	25475	Change oil and filters	7703 Filter
			Replace the fuel filter	3587 Filter
			Replace the air filter	3588 Filter
			Replace two marker lamps	2798 Filter
			Grease body and chassis	2, 3050 Lamps
11/27/19	418885		Transmission yoke back out	25093516 Bolt
			Replace the bolt and seal	25623778 Seal
12/14/19	419830		Emission test, fail	RD570881P Compressor
12/24/19	420241		Replace the A/C compressor its belt and weld the bracket	A/C Belt
2/13/20	423195		Adjust brakes	Auto tarp
2/17/20	423312	25836	Replace the tarp	
			Safety inspection	L Bracket
2/19/20	423556		Replace the control valve mounting bracket	
3/10/20	424298		New driver got the transmission stuck in gear	
			R&R the floorboards and the shift tower, place shifting forks	
			back into neutral I	
4/13/20	424357	25474	Grease body and chassis	4050 Lamp
			Replace the right inside tail light	40197 Bearing
			Replace the first carrier bearing	
			Have the driveshaft shop weld in a spline end	6342711 Yoke
			Replace the yoke and U-joint	5676X U-joint
				25190654 Sensor
5/11/20	425400		Replace the exhaust temperature sensor J	
5/16/20	425918		Tighten the seats X bracket bolts J	3157-M7162 Mirror glass
5/28/20	426829		Replace the west coast mirror glass	
6/5/20	427321	26203	Found the fuel cap off, and it rain	3588 Filter
			Drain water from the tank, change fuel filters S	3587 Filter
6/8/20			Road call, Deal, stuck in first, R&R the shift tower. Line up the	
			shifting forks, K	SCB500 Brake
6/9/20	427547		Replace the clutch brake	
6/20/20	428429		Replace the tarps cross bar J	
7/22/20	430477		Repair the left rear tarp spring mount, bent upward M	
			Install and wire up the proper headlight switch J	
			Cut out and removed the tail and side light wiring	
			Install new wiring with loom, J	
			Replace the cab clearance lamp relay J	
8/10/20	431556		Stuck in gear, R&R the shift tower. Line up the forks K	95943 Clip
			Replace a headlight adjuster clip J	
8/11/20	431661		Reattach the tarp to the roller J	2, 21939298 Filters
8/13/20	431775	26592	Change oil and filters S	7703 Filter
			Replace the fuel filter S	3587 Filter
			Replace the air filter S	3588 Filter
			Grease body and chassis I	2798 Filter
			Replace the right front spring pin, drill and tap the lock bolt S	R303715 Spring pin
			Replace the center bolt, U-bolts and dowel pin S I	25160299 Lock bolt
				CB1210 Center bolt
				CBL12 Spacer
				M1487 Dowel pin
			Weld a reinforce plate on the left trunnion bracket	

Date	Miles	Hours	Description	Parts
9/8/20			Stuck in gear at Mazza, K	25133923 Hose
9/10/20	432944		Replace the pipe to manifold aftercooler hose J I	20705898 Clamp
			Replace one clamp I	M-G-A4285 Hold down kit
			Install the "Hooker" auto rear hold downs M K I	
11/6/20	433341		Adjust the clutch S	
11/13/20	433527	25731	Grease body S	
			Check pressure, OK, J	
			Repair a tail light wire S	1108713 Filter
			Replace the hydraulic filter S	
			Emissions test	
2/25/21	434005			
3/8/21	434041	26786		
3/19/21	434424		Secure the right door latch I	
3/20/21			Grease body J	
			Adjust brakes J	
3/27/21	435016		Adjust the clutch S	
			Charge the AC S	
4/5/21	435633		Replace the turn signal switch I	915Y703 Switch
			Replace a rear marker K	G3002 Lamp
4/10/21	436158		Repair the wires to the windshield washer J	
			Replace the left window lower weather stripping & lube the regulator J	2, 25155441 Weather stripping
5/3/21	437844		Weld up the crack on the right hoist sub frame M	
5/8/21	438528		Weld the right rear tarp arm mount fast M	
5/15/21	439225		Rebuild the rear light box M	
5/17/21			Towed in, Ocean, Accident	
5/19/21	439418	27187	Reposition the right front axle, replace the center bolt, spacer, U-bolts S	See part sheet
			Replace the shock absorber, and fender extension with supports S	
			Replace one wheel stud, hub cap and tire S	
5/31/21	439879		Replace the clutch and the pilot bearing I	
6/10/21	440888		Weld the right front tarp arm mount fast M	
6/30/21	442544		Replace the frame to hoist hoses S	2, 3/4x3', 16MJIC Hoses
7/3/21	442722		Replace the left front center bolt S	
7/9/21	443158		Replace the rear roller and its axle K I	
			Replace the right rear rear axle slack adjuster, S-cam & seal K	2210K7421 S-cam
				370031A Seal
				40010144 Slack adjuster
7/12/21	443268		Replace the left rear rear brake can K	30/30 Brake can
7/16/21	443733	27530	Change oil and filters S	2, 21939298 Filters
				7703 Filter
			Replace the fuel filter S	3587 Filter
				3588 Filter
				2798 Filter
			Blow out the air filter S	
			Grease body and chassis S	
			Replace the brakes on the right 1st rear axle S	XK3124707QP Brake kit
			Replace the left 1st rear axle brake can S	30/30 Brake can
8/21/21	445593		Replace the driver's seat shock absorber S	6222082001 Absorber
8/24/21	446831		Replace the right headlight adjustment assembly J	95943 Adjuster
9/2/21	447495		Replace the water pump F	316GC551M3X Pump
9/25/21	449037		Adjust brakes J	
10/9/21	450232		Replace a rear marker K	3050 Lamp
			Repair the left tarper arm mount, hit a pole M	
10/17/21			Towed in, Ocean, Carrier bearing broke	
			Replace the suction hose F	8.5' of 2" Suction hose
			Replace the front carrier bracket and the bearing K	
			Replace the left hooker cylinder K	
10/20/21	451016		Stuck in gear S	
			Replace the shifter S	
10/28/21	451263		Grease body S	
			Straighten out the left hooker S	
10/29/21			Road call, Long Branch, stuck in mud	
10/30/21	451360		Realign the rear spring on the right trunnion K	R303698 Thrust washer
11/15/21	452425		Repair the right tarp arm I	

Date	Miles	Hours	Description	Parts
11/18/21	452985		Grease the body F	
12/14/21			Tighten the torque rods F	215195379 Cap
12/18/21	455015	28425	Replace the fuel cap J	2, 21939298 Filters
			Change oil and filters S	7703 Filter
			Replace the fuel filter S	3587 Filter
				3588 Filter
				2798 Filter
			Replace the air filter S	
			Grease body and chassis S	2, XK3124707QP Brake kits
			Replace the front brakes S	
12/28/21	455660		Replace the left lower hinge I	
2/5/22	458381		Adjust clutch J	2, 30700 Grommets
2/11/22	459114		Replace two rear marker light grommets K	
			Weld up the crack at the left rear tarp mount M	25185770 Elbow pipe
2/19/22	459389		Repair the exhaust system M	HD-14C-500A Y-pipe
				GR-R5I-4IA Adaptor
				733-3225 Clamp
3/1/22	460031		Tighten the pivot bolt on the drivers seat F	3, M-G-521-A Rollers
			Replace three rear side rollers S	4, M-G-1525 Pins
3/5/22	460442		Replace the right second side roller and its pin M	M-G-522-AO Roller
				M-G-1746W Pin mount
				M-G-552-W Washer
				M-G-1525 Cotter pin
				1156 Bulb
3/7/22	460590		Replace the right front turn signal bulb K	
3/8/22	460694		Adjust brakes S	
3/15/22	461102		Weld the driver's step D	
			Replace the right rear rear, brakes, seal and S-cam S	
3/17/22	461307		Grease the body K	
4/2/22	462277		Weld fast the right tarp arm bracket M	76701 Kit
4/9/22	462740		Replace the arm spacers J	95943 Clip
4/16/22	463127		Replace the left headlight adjuster clip J	6 5-4-4271-1X Yoke
			Replace the front rear front yoke S	23396652 Seal
			Replace the front rear rear pinon seal S	25624339 Seal
			Replace the rear rear pinion seal S	
			Adjust brakes S	
4/25/22	463859		Towed in, Wall, Front carrier bearing bracket broke	25160106 Bracket
			Replace the bucket J	
4/28/22	463976		Adjust brakes K	
5/6/22	464851		Check out and adjust brakes S	760810 Collar
			Replace a tarp collar on the cross bar center the tarp J	
			Safety inspection S	
5/14/22	465463		Make up and installed a mud flap bracket M	2, Mud flaps
			Replace the mud flaps M	
5/23/22	466069		Sent to R&H for the rear suspension	
6/3/22	466210		Back from R&H	2, PX31925C Batteries
			Replace two batteries J	
			Adjust brakes J	
6/17/22	466540		Weld the left rear tarp mount M	RD442724R Thermostat
6/25/22	467037		Replace the AC thermostat J	1' of 801-16 Hose
			Replace the hose to the coolant reservoir S J	
7/6/22	467486		Repair the right tarp arm J	
7/7/22	467599		Adjust brakes and clutch S Da	
7/9/22	467742		Align the tarp arms J	2, 21939298 Filters
7/11/22	467873	29253	Change oil and filters Da	7703 Filter
			Replace the fuel filter Da	3587 Filter
				3588 Filter
				2798 Filter
			Replace the air filter Da	
			Grease body and chassis Da	

Brake type d

Brake Type
Designation

Date	Miles	Hours	Description	
7/16/22	467989		Replace the left rear rear wheel seal and brakes S	370031A Seal XK3124707QP Brake kit
8/4/22	469335		Adjust brakes K	
8/12/22	469746		Replace the tarp J	
8/25/22	470523		Charge a/c J	
8/30/22	470801		Adjust brakes S	
9/7/22	471035		Replace the left front rear S- cam, and its bracket S	E9659 S-cam
			Replace the brakes and drum S	A3211M5629 Bracket XK3124707QP Brake kit 3600 Drum
9/17/22	471784		Adjust brakes and clutch K	
9/28/22	472506		Road call, Ocean, stuck in gear S	
9/29/22	472607		Replace the chain on the ICC Bar S	
			Rebolt the rear licenses plat back on S	
10/7/22	473164		Adjust brakes K	
			Grease hookers K	
10/19/22	473862		Replace the right front slack adjuster K	40010011 Adjuster
			Replace the left hub cap K	1691 Cap
10/20/22	473953		Replace the left fender mirror and bracket J	Used mirror assembly
11/16/22	475335		Replace the right inside tail light pigtail K	67000 Pigtail
11/19/22	475565		Adjust clutch J	
12/23/22	477058		Replace a rear marker light K	3050 Lamp
12/28/22	477003		Replace the left wiper arm and blade J	25109820 Wiper arm 6-018-1 Blade
1/4/23	477495		Adjust clutch S	
1/11/23	477950	30016	Grease body A	
			Replace a cab marker A	1075AD Lamp
1/20/23	478653		Repair the left tarp arm mount M	
			Adjust brakes K	
1/27/23	429112		Remove the transmission, send to Camerota, gets stuck in 2nd	
2/10/23			R&R the flywheel for resurfacing S A	
2/16/23			Received the transmission back	
			Install with a new clutch, clutch brake, pilot bearing, S A	Rebuilt transmission 308925-98 Clutch BK313 Clutch brake 306VVL Bearing 6136 Shaft 6134 Shaft 562 U1588A Flange 2, X007824 Clamps
			Install new clutch shafts S	
			Weld a turbo flange on the exhaust pipe M	
2/27/23			Road call, Mazza, stuck in gear K	
3/1/23	480106		Adjust clutch S	
3/4/23	480428	31210	Change oil and filters K	2, 21939298 Filters
			Replace the fuel filter K	7703 Filter 3587 Filter 3588 Filter 2798 Filter
			Replace the air filter J	
3/11/23	480830		Grease body and chassis A	
			Adjust brakes S	
3/15/23	481166		Replace the right outside tail light J	4050 Lamp
3/21/23	481809		Replace the PTO switch	25164287 Switch
3/27/23	482178		Replace the parking brake valve S	276567X Valve
4/8/23	483249		Replace the Caps on the cooling tanks J	25005579 Cap
			Adjust brakes S	063415A Cap
			Repair the tail lights S	
			Replace the tarp and one spacer J	8 x 28 Tarp 76810 Spacer
4/17/23	483751		Road call, 2X, stuck in gear, 1st S, 2nd K	
			Replace the right hub cap K	1691 Cap
4/25/23	484386		Road Call, Deal, PTO wire broke under the cab K	
5/13/23	485974		Repair the right hold downs J	
			Replace a O-ring at the A/C compressor and charge J	
5/23/23	486707		Repair the tarp cross bar K	

Date	Miles	Hours	Description	Parts
5/29/23	487132		Adjust the left tarp arm J Reinstall the left mid body marker lamp J Reinstall the left front rear slack adjuster, adjust brakes J Blow out the radiator S	
6/2/23	487132		Road call, Middletown, Left hold down broke free K Weld the left hold down back on, M Hook up the air lines S	
6/10/23	488459		Replace the left hood hinge rod eye J	25037088 Eye
6/30/23	490369		Replace the radiator S Replace the front motor mounts S	811 62102 Radiator 2, 022586 Hose clamps 4, 25164179 Mounts 2, 25095339 Bolts 2, 25089732 Nuts 2, 25626139 Spacers ROLL-76800 Elbow Steel channel Steel tube Steel pipe Steel plate 2, R-F 2001 Fenders 62-707R Pivot pin 2, 62-702 Arms 46220 Arm
7/21/23	491826		Replace the left tarp 90, elbow J	
7/27/23	492079		Repair the right rear damage from hitting a tree M	
			Replace the right pivot pin in the spring box J Replace both tarper arms M	
			Rebolt the left hooker cylinder K Weld back the right rear tarp bracket M	
8/9/23	493048		Rebolt the rear right fender J	
8/17/23	493785		Grease the hooker's J	
8/25/23	494638		Adjust brakes J	
8/29/23	494891		Change oil and filters K A	2, 21939298 Filters 7703 Filter 3587 Filter 3588 Filter 21074769 Filter kit
9/4/23	495294	31241	Replace the fuel filter K A	
			Replace the Centrix oil housing S Grease body and chassis A Safety inspection J	
9/15/23	496377		Replace the parking brake valve with its knob K	108235N Knob 276567X Valve 4050 Lamp
			Replace the left tail light K R & R the air tank S Repair the air tank M	
9/21/23	496965		Came in with the diff lock on, tandem drive shaft missing, front of the rear yoke broke and the shaft walk out. Drill and remove the broken bolt R Replace the yoke, drive shaft R	Used driveshaft 17TYS3260A Yoke 2, XK3124707QP Brake kits 2, 151.6700BATR Drums
10/10/23	498133		Replace the rear rear axle brakes, drums and seals R A	
			Grease body A	
10/26/23	498882		Replace the left sun visor clip J	25157939 Clip
10/28/23	499022		Replace the revers switch K	25157099 Switch
11/2/23	499468		Replace the right cab work light J	80360 Lamp
11/18/23	500748		Replace the right tarp work light J R&R the outside valve controls, clean and reboot J Replace a O-ring on the winch spool J	2, M-G-A3760 Boots M-G-A4716 Cylinder
11/29/23	501562		Replace the right hooker cylinder J	
12/2/23	501799		Grease body S Replace the left fender mirror S Replace the fuel cap S	206-6 Mirror 25195379 Cap 3050 Lamp
12/7/23	502292		Replace a missing marker K	
12/23/23	503318		Adjust clutch J Grease body J	

Date	Miles	Hours	Description	Parts
1/5/24	504138		Replace a after cooler boot J	8178232 Boot 2, # 48 clamps 2, #10 Clamps Used mirror
1/15/24	504869		Replace the right west coast mirror S Replace the air dryer R Replace the left inside door linkage R	109685X dryer 25625220 inside latch rod
2/20/24	507289		Clutch adjustment K	
2/24/24	507641		Replace the driver seat S Replace the windshield washer bottle cap	2339131546 Seat 25171865 Cap
3/4/24			Replace a headlight assembly	21077000 Assembly
3/28/24	507397		Replace the right wiper blade P	6-018-1 Blade
4/1/24	510522		Replace the front rear brakes, cam bushing and cams. K, P.	2, 3600AX Drums 2, XK3124707QP Brake kits 2, 3930104 Seals KIT8042 Bushing kit 2210H7522 S-Cam 2210L7422 S-Cam 40010144 Slack adjuster 135.2832 Slack adjuster
4/19/24			Replace the turbo pipe and clamp	25153474 Pipe 25174573 Clamp 25156115 Pipe 8181264 Clamp 2, X007824 Clamps 25165870 Clamp
4/29/24	510522		Replace the transmission, Warranty G, S, P, RD.	4, 752.657018X Strap kits
5/3/24			Replace a cab and a side marker lamp.	BK313 Clutch brake 25130491 Cab marker 10276Y Marker
5/7/24	511207		Replace the container lock piston. K	MTM-A4716 Cylinder
5/20/24	512063		Replace the left container lock air cylinder. P	MTM-A4716 Cylinder
5/23/24	512483		Repair the winch actuator air line. K	
5/28/24	512729		Repair windshield washer fluid hose. P	
6/17/24	513899		Road call flat tire K	
6/17/24	514180		Adjusted steering stops. RD Replaced all three batteries. S Replace the right rear rear tires. S Remove the front bumper, extract broken bolts and install with new hardware. S PM SERVICE. S	3, 7236 Batteries 2, 1791 Oil Filters 7703 Oil filter 11 Gals 10W40 Oil 3587 Fuel filter 3588 Fuel filter 2798 Air filter
6/18/24	514303		Replace the left rear rear outside tire K	
6/20/24	514534		Replace the back up alarm. P	
7/8/24	515754		Check the A/C System. P Adjust clutch. RD	7301067 Alarm
7/9/24	515859		Repaire the left tarp arm. K	
7/19/24	516513		Replace the revers switch, RD, S	
7/30/24	517257		Charged A/C, Repair the work light. P	25157099 Switch
8/3/24	517627		Replaced steering shaft u-joints and bearing, P	2, 5103X U-joints 25107551 Bearing
8/13/24	518115		Replace the spool seals. P Replace the fuel pump, cleaned corrosion from relay box, replaced relays. P, RD	2, 0614153 Seal kits 85013282 Pump
8/15/24	518214		Replace the front tires, Realign the tie rods. RD, P	32GB515M Housing
8/17/24	518329		Tail lights out. Repair the wiring. P	
8/19/24	518438		Replace two hyd lines on valve body to reeving piston tube under bed. P	

Date	Miles	Hours	Description	Parts
8/26/24	518935		Rewire the revers alarm and all rear lighting. P, RD	2, 4060C Revers lamps 15-961 Junction box Used straps
9/7/24	520044		Replace the fuel tank straps S	
9/17/24	520711		Replaced the air compressor to governor air line K	
9/18/24	520867		Repair the tarp arm K	
9/19/24	521005		Recharge the A/C system P	
9/14/24	520504		D.O.T INSPECTION P	
10/10/24	522685		Clutch adjustment RD, S	
			Repair a power steering hose clamp S	
			Replace the left rear rear tires S	
10/16/24	522945		Replaced winch cable, S, M	CB7 3X128 Cable
11/25/24	525734		Repair a short in the dash for the marker lights. RD, S	2, 1791 Oil Filters
11/27/24	525978		PM OIL CHANGE S	7703 Oil filter 3587 Fuel filter 3588 Oil filter 2798 Air filter
			Air brake antifreeze S	3050A Lamp
12/9/24	528639		Replace a rear marker light. P	
12/11/24	526769		Control valve bracket broken, Make a new bracket and install, RD, M	
12/13/24	527029		Coolant leak, Replaced two hose clamps. S	
12/28/24	527915		PM GREASE Don	
1/20/25	529156		Right front tire low. Tighten the valve stem. F	
2/12/25	530753		Adjust the clutch K	3050 Lamp
			Replace a marker light K	
2/22/25			Road call, Mazza, Driveshaft spins, pull to the shop with a chain K	
			Driveshaft strip, R&R the drive shaft for rebuilding.	Rebuilt driveshaft
			Install the drive shaft with U-joint straps. K	2, UJ476-10 Strap kit
3/12/25	531449		Grease body and chassis F	

Basic Service History

Truck 88

Oil & Filter	Grease	Fuel Filter Primary	Fuel Filter Secondary	Air Filter	Body	Grease
3/28/16	3/28/16	4/15/16	4/15/16	3/28/16	3/28/16	12/18/21
336514	336514	337009	337009	336514	336514	455015
20061	20061	20067	20067	20061	20061	28425
6/14/16	6/14/16	6/14/16	6/14/16	2/4/17	6/14/16	3/17/22
337332	337332	337332	337332	365452	337332	461307
				21611		
9/3/16	9/3/16	9/3/16	9/3/16		9/3/16	7/11/22
347848	347848	347848	347848	10/7/17	347848	467873
20683	20683	20683	20683	375902	20683	29253
				22422		
11/12/16	11/12/16	11/12/16	11/12/16		11/12/16	1/11/23
355960	355960	355960	355960	2/9/19	355960	477950
21112	21112	21112	21112	397214	21112	30016
				23981		
2/4/17	2/4/17	2/4/17	2/4/17		12/28/18	3/4/23
365452	365452	365452	365452	7/4/19	360881	480428
21611	21611	21611	21611	408733	21374	30210
				24821		
10/7/17	10/7/17	10/7/17	10/7/17		2/4/17	9/4/23
375902	375902	375902	375902	11/18/19	365452	495294
22422	22422	22422	22422	418249	21611	31241
				25475		
5/5/18	5/5/18	5/5/18	5/5/18		8/12/17	10/10/23
385890	385890	385890	385890	8/13/20	5/6/17	498133
23137	23137	23137	23137	431775	22079	
				26892		12/2/23
2/9/19	2/9/19	2/9/19	2/9/19		10/7/17	501799
397214	397214	397214	397214	12/18/21	375902	
23981	23981	23981	23981	455015	22422	12/23/23
				28425		503318
7/4/19	5/4/19	7/4/19	7/4/19		4/28/18	
408733	404306	408733	408733	7/11/22	385125	2/3/24
24821	24507	24821	24821	467873	23095	506179
				29253		
11/18/19	11/18/19	11/18/19	11/18/19		5/5/18	6/17/24
418249	418249	418249	418249	3/4/23	385890	514180
25475	25475	25475	25475	480428	23137	
				30210		11/27/24
8/13/20	8/13/20	6/5/20	6/5/20		6/1/18	525978
431775	431775	427321	427321	2/3/24	387330	
26892	26892	26203	26203	506179	23257	12/28/24
				32081		527915
7/17/21	7/17/21	8/13/20	8/13/20		2/9/19	
443733	443733	431775	431775	6/17/24	397214	3/12/25
27530	27530	26892	26892	514180	23981	531449
12/18/21	12/18/21	7/17/21	7/17/21	11/27/24	5/4/19	
455015	455015	443733	443733	525978	404306	
28425	28425	27530	27530		24507	
7/11/22	7/11/22	12/18/21	12/18/21		8/10/19	
467873	467873	455015	455015		411370	
29253	29253	28425	28425		25024	
3/4/23	3/4/23	7/11/22	7/11/22		11/18/19	
480428	480428	467873	467873		418249	
30210	30210	29253	29253		25478	
9/4/23	9/4/23	3/4/23	3/4/23		8/13/20	
495294	495294	480428	480428		431775	
31241	31241	30210	30210		26892	
2/3/24	2/3/24	9/4/23	9/4/23		11/13/20	
506179	506179	495294	495294		433527	
32081	32081	31241	31241		25731	
6/17/24	6/17/24	2/3/24	2/3/24		7/17/21	
514180	514180	506179	506179		443733	
		32081	32081		27530	
11/27/24	11/27/24				10/28/21	
525978	525978	6/17/24	6/17/24		451263	
		514180	514180			
	12/28/24				11/18/21	
	527915	11/27/24	11/27/24		452985	
		525978	525978			
	3/12/25					
	531449					

Date	Miles	Hours	Front Shoes	Drums	Rear Shoes 1st Axle	Drums	Rear Shoes 2nd Axle	Drums	Slacks, Cams, Chambers, etc
3/28/16	336514						Both	No	
7/13/16	41334								Air compressor
9/7/16	348223								Right rear rear seal & outer bearing
2/5/17	365827				Right	No			Seal
11/4/17	378034		Both	Yes					Left front slack adjuster
4/7/18	383683				Right	Yes			
1/28/19	396573								Foot, relay & spring brake valves
2/19/19	387868								Relay valves
6/19/19	407671						Left	No	Seal
6/24/19	407923				Left	No			Right 1st rear slack adjuster
7/10/21	443158								Right rear rear slack adjuster & S-cam
7/12/21	443268								Right rear rear brake can
7/17/21	443733				Left	No			Right 1st rear brake can
12/18/21	455015		Both	No					
3/15/22	461102						Right	No	S-cam, bushings, seal
7/16/22	467989								Left rear rear wheel seal
9/7/22	471035				Left	Yes			Brake cam bracket, S-cam
10/19/22	473862								Right front slack adjuster
3/21/23	481809								Parking brake valve
9/15/23	496377								Parking brake valve
10/10/23	498133						Both	Yes	Seals
1/15/24	504869								Air dryer
4/1/24	510522				Both	Yes			S-cams and bushings, seals

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used	Total	Total week	Week
Filter	F&C	NAPA	1791XE	Oil filter	3/28/16		y	20.26	2	40.52	
Oil	Red Drum	Sinopec	15W40	Engine oil	3/28/16	y	7.00	11	77.00		
Filter	F&C	NAPA	2798	Air filter	3/28/16	y	61.69	1	61.69		
Brakes	Bergey's	Meritor	KK3124707QP	Rear brake kit	3/28/16	y	49.19	2	98.39		
Blade	F&C	NAPA	60-018	Windshield wiper blade	3/30/16	y	9.48	2	18.96		
Air bag	Bergey's	Goodyear	25166846	Cab's air bag	3/30/16	y	63.91	1	63.91	360.47	3/27/16
Pigtail	Sosmetal	Trucklite	94902-3	2 Wire pigtail	4/6/16	y	1.59	1	1.59		
Wire end	Sosmetal	3M	Red	Butt connector	4/6/16	y	0.17	2	0.34	1.93	4/3/16
Filter	F&C	NAPA	3587	Secondary fuel filter	4/15/16	y	11.92	1	11.92		
Filter	F&C	NAPA	3588	Primary fuel filter	4/15/16	y	9.53	1	9.53	21.45	4/10/16
Hose	Made	Parker	3/4x24", 16MJIC 16FJIC	Rear hoist hoses	4/19/16	y	26.93	2	53.86	53.86	4/17/16
Brake		Snap on clutch	SCB200	Clutch brake	6/25/16	y	29.28	1	29.28	29.28	6/19/16
Air compressor	D&W	Walco	S9111530557	Air compressor, rebuilt	7/13/16		y	611.07	1	611.07	
Hose	Allied	Parker	1/2 x 1", 8XSAEF Hose	Air compressor cooling	7/13/16		y	35.56	1	35.56	646.63 7/10/16
Hose	Van Sant	Weather Head	3/4x3, 16FJIC	Lift cylinder	9/2/16		y	46.35	1	46.35	
Hose	Van Sant		3/4x7, 12FJIC 12FJIC 45	Pump to valve	9/2/16		y	138.31	1	138.31	
Filter	Bergey's	Mack	21939298	Oil filter	9/3/16	y	7.51	2	15.02		
Filter	F&C	NAPA	7703	Oil, Rotor kit	9/3/16	y	28.38	1	28.38		
Oil	Red Drum	Sinopec	15W40	Engine oil	9/3/16	y	7.00	11	77.00		
Filter	F&C	NAPA	3587	Secondary fuel filter	9/3/16	y	11.92	1	11.92		
Filter	F&C	NAPA	3588	Primary fuel filter	9/3/16	y	9.53	1	9.53	326.51	9/28/16
Seal	F&C	National	370031A *	Wheel seal, rear	9/7/16	y	29.08	1	29.08		
Bearing	F&C	Timken	SET426	Wheel bearing, rear outer kit	9/7/16	y	69.54	1	69.54		
Oil	Red Drum	Sinopec	80W140	Gear lube	9/7/16	y	9.00	0.5	4.50	103.12	9/4/16
Filter	Bergey's	Mack	21939298	Oil filter	11/12/16	y	7.51	2	15.02		
Filter	F&C	NAPA	7713	Oil rotor filter	11/12/16	y	28.38	1	28.38		
Oil	Red Drum	Sinopec	15W40	Engine oil	11/12/16	y	7.00	11	77.00		
Filter	F&C	NAPA	3587	Secondary fuel filter	11/12/16	y	11.92	1	11.92		
Filter	F&C	NAPA	3588	Primary fuel filter	11/12/16	y	9.53	1	9.53	141.85	11/6/16
Boot	Holtz	Holtz	M-G-A3760	Bracket valve handle boot	12/17/16	y	7.28	2	14.56	14.56	12/11/16
										1699.66	
Bulb	Sosmetal	Elko	1156	Turn single bulb	1/12/17	y	0.29	1	0.29		
Wire end	Sosmetal	3M	Blue	Butt connectors	1/12/17	y	0.48	4	1.92	2.21	1/8/17
Lamp	Bergey's	Vehicle Safety	4805AAY4	Front turn single	1/18/17		y	21.61	1	21.61	
Wire end	Sosmetal	3M	Blue	Butt connectors	1/18/17	y	0.48	2	0.96	22.57	1/15/17
Filter	Bergey's	Mack	21939298	Oil filter	2/4/17	y	7.51	2	15.02		
Filter	F&C	NAPA	7703	Oil, Rotor kit	2/4/17	y	28.38	1	28.38		
Oil	Red Drum	Sinopec	15W40	Engine oil	2/4/17	y	6.39	11	70.29		
Filter	F&C	NAPA	3587	Secondary fuel filter	2/4/17	y	11.92	1	11.92		
Filter	F&C	NAPA	3588	Primary fuel filter	2/4/17	y	9.53	1	9.53		
Filter	F&C	NAPA	2798	Air filter	2/4/17	y	61.59	1	61.59	196.73	1/29/17

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used Total	Total week	Week
Roller	Holtz	Holtz	M-G-521-AO	Side roller, 3"	2/10/17					
Pin	Holtz	Holtz	M-G-2185W	Side roller pin, 3"	2/10/17	Y	30.00	1	30.00	
Washer	Holtz	Holtz	M-G-552-W	Washer for roller	2/10/17	Y	18.37	1	18.37	
Pin	Holtz	Holtz	M-G-1525	Cotter pin for roller	2/10/17	Y	0.99	1	0.99	
Pad	Bergey's	Sternco	12014	Spring pad, lower	2/15/17	Y	0.50	1	0.50	49.86
Pad	Bergey's	Mack	25121508	Spring pad, upper	2/15/17	Y	90.84	2	181.68	
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	2/15/17	Y	32.96	2	65.90	
Clutch	Bergey's	Sanden	4639-9931	AC Clutch	2/15/17	Y	49.69	1	49.69	297.27
Pin	R&H	Automann	MMCK48	Axle spacer pin	5/24/17		120.02	1	120.02	120.02
Cap	Bergey's	Mack	25195379	Fuel cap 3" Vented	6/17/17	Y	3.69	1	3.69	3.69
Lamp	F&C	NAPA	3050	2" LED marker red	6/24/17	Y	44.79	1	44.79	44.79
Flasher	F&C	NAPA	EL12	Two prong flasher, round	6/27/17	Y	5.49	1	5.49	5.49
Lamp	Bergey's	Mack	4805AAY4	Front mount turn single lamp	7/22/17	Y	12.05	1	12.05	12.05
Trim	Bergey's	Mack	25171344	Top trim panel	7/29/17	Y	21.81	1	21.81	21.81
Radio	Bergey's	Mack	5165-CQCX160USA	Radio	8/12/17	Y	203.12	1	203.12	
Filter		McNeilus	1108713	Hydraulic	8/12/17	Y	134.77	1	134.77	
Filter	F&C	NAPA	1348	Hydraulic Breather	8/12/17	Y	11.47	1	11.47	
Bar	Fazzio's	Buyers	1903060	Hold down winch bar	8/12/17	Y	3.65	1	3.65	
Horn	Bergey's	Mack	20766981	Electric horn	8/12/17	Y	14.95	1	14.95	
Cap	Bergey's	SKF	1458-1643	Hub cap	8/12/17	Y	22.41	1	22.41	390.37
Screw	Bergey's	Mack	130AX84	Door guide screw	8/17/17	Y	9.75	1	9.75	
Bulb	Sosmetal	Wagner	37	Indicator light bulb	8/17/17	Y	1.51	1	1.51	
Holder	F&C	NAPA	782-3125	Fuse holder ATC/ATO	8/17/17	Y	0.30	1	0.30	
Wire end	Ralph K Badmann	3M	31330	Butt Connector	8/19/17	Y	3.29	1	3.29	
Fuse	Sosmetal	Sosmetal	615221	Fuse, ATO 20A	8/19/17	Y	0.48	2	0.96	
O-ring	Trans Bearing		183	Return filter housing	8/19/17	Y	0.21	1	0.21	16.02
Pedal	Bergey's	Williams Controls	25174960	Accelerator pedal	9/1/17	Y	1.49	1	1.49	1.49
Mirror		Mirror Tech	207-6	Mirror, 6" Fender	9/8/17	Y	307.01	1	307.01	307.01
Knob	Bergey's	Bendix	745-108235N	Knob and pin, PP-1 valve	9/11/17	Y	25.50	1	25.50	25.50
Bracket	Holtz	Holtz	M-G-A3640	Bracket valve handle	9/19/17	Y	12.37	1	12.37	
Strap	Holtz	Holtz	M-G-A3306	Rear hold down, strap	9/22/17		105.47	2	210.94	223.31
Filter	Bergey's	Mack	21939298	Oil filter	10/4/17	Y	15.00	2	30.00	
Filter	F&C	NAPA	7713	Oil rotor filter	10/7/17	Y	7.51	2	15.02	
Oil	Red Drum	Sinopec	15W40	Engine oil	10/7/17	Y	28.38	1	28.38	
Filter	F&C	NAPA	3567	Secondary fuel filter	10/7/17	Y	7.00	11	77.00	
Filter	F&C	NAPA	3588	Primary fuel filter	10/7/17	Y	11.92	1	11.92	
Filter	F&C	NAPA	2798	Air filter	10/7/17	Y	9.53	1	9.53	
Tube	Bergey's	Mack	25089930	Surge tube	10/7/17	Y	61.59	1	61.59	
Roller	Holtz	Holtz	M-G-521-AO	Side roller, 3"	10/7/17	Y	44.18	1	44.18	
					10/7/17	Y	30.00	6	180.00	457.62

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used	Total	Total week	Week
Roller	Holtz	Holtz	M-G-521-AO	Side roller, 3"	2/10/17	y	30.00	1	30.00		
Pin	Holtz	Holtz	M-G-2185W	Side roller pin, 3"	2/10/17	y	18.37	1	18.37		
Washer	Holtz	Holtz	M-G-552-W	Washer for roller	2/10/17	y	0.99	1	0.99		
Pin	Holtz	Holtz	M-G-1525	Cotter pin for roller	2/10/17	y	0.50	1	0.50	49.86	2/5/17
Pad	Bergey's	Stemco	12014	Spring pad, lower	2/15/17	y	90.84	2	181.68		
Pad	Bergey's	Mack	25121508	Spring pad, upper	2/15/17	y	32.95	2	65.90		
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	2/15/17	y	49.69	1	49.69	297.27	2/12/17
Clutch	Bergey's	Sanden	4639-9931	AC Clutch	5/24/17		120.02	1	120.02	120.02	5/21/17
Pin	R&H	Automann	MMCK48	Axle spacer pin	6/17/17		3.69	1	3.69	3.69	6/11/17
Cap	Bergey's	Mack	25195379	Fuel cap 3" Vented	6/24/17		44.79	1	44.79	44.79	6/18/17
Lamp	F&C	NAPA	3050	2" LED marker red	6/27/17	y	5.49	1	5.49	5.49	6/25/17
Flasher	F&C	NAPA	EL12	Two prong flasher, round	7/22/17	y	12.05		12.05	12.05	7/16/17
Lamp	Bergey's	Mack	4805AAY4	Front mount turn single lamp	7/29/17	y	21.61	1	21.61	21.61	7/13/17
Trim	Bergey's	Mack	25171344	Top trim panel	8/12/17		203.12	1	203.12		
Radio	Bergey's	Mack	5165-CQCX160U5A	Radio	8/12/17		134.77	1	134.77		
Filter		McNeilus	1108713	Hydraulic	8/12/17	y	11.47	1	11.47		
Filter	F&C	NAPA	1348	Hydraulic Breather	8/12/17	y	3.65	1	3.65		
Bar	Fazzie's	Buyers	1903060	Hold down winch bar	8/12/17		14.95	1	14.95		
Horn	Bergey's	Mack	20766981	Electric horn	8/12/17	y	22.41	1	22.41	390.00	8/6/17
Cap	Bergey's	SKF	1458-1643	Hub cap	8/17/17	y	9.75	1	9.75		
Screw	Bergey's	Mack	130AX84	Door guide screw	8/17/17	y	1.51	1	1.51		
Bulb	Sosmetal	Wagner	37	Indicator light bulb	8/17/17	y	0.30	1	0.30		
Holder	F&C	NAPA	782-3125	Fuse holder ATC/ATO	8/19/17	y	3.29	1	3.29		
Wire end	Ralph K Badmann	3M	31330	Butt Connector	8/19/17	y	0.48	2	0.96		
Fuse	Sosmetal	Sosmetal	615221	Fuse, ATO 20A	8/19/17	y	0.21	1	0.21	16.02	8/13/17
O-ring	Trans Bearing		183	Return filter housing	9/1/17		1.49	1	1.49	1.49	8/27/17
Pedal	Bergey's	Williams Controls	25174960	Accelerator pedal	9/8/17	y	307.01	1	307.01	307.01	9/3/17
Mirror		Mirror Tech	207-6	Mirror, 6" Fender	9/11/17	y	25.50	1	25.50	25.50	9/10/17
Knob	Bergey's	Bendix	745-108235N	Knob and pin, PP-1 valve	9/19/17	y	12.37	1	12.37		
Bracket	Holtz	Holtz	M-G-A3640	Bracket valve handle	9/22/17		105.47	2	210.94	223.31	9/17/17
Strap	Holtz	Holtz	M-G-A3306	Rear hold down, strap	10/4/17	y	15.00	2	30.00		
Filter	Bergey's	Mack	21939298	Oil filter	10/7/17	y	7.51	2	15.02		
Filter	F&C	NAPA	7713	Oil rotor filter	10/7/17	y	28.38	1	28.38		
Oil	Red Drum	Sinopec	15W40	Engine oil	10/7/17	y	6.39	11	70.29		
Filter	F&C	NAPA	3587	Secondary fuel filter	10/7/17	y	11.92	1	11.92		
Filter	F&C	NAPA	3588	Primary fuel filter	10/7/17	y	9.53	1	9.53		
Filter	F&C	NAPA	2796	Air filter	10/7/17	y	61.59	1	61.59		
Tube	Bergey's	Mack	25089930	Surge tube	10/7/17	y	44.18	1	44.18		
Roller	Holtz	Holtz	M-G-521-AO	Side roller, 3"	10/7/17	y	30.00	6	180.00		
Pin	Holtz	Holtz	M-G-1525	Cotter pin for roller	10/7/17	y	0.50	6	3.00	453.91	10/1/17

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used	Total	Total week	Week
Hose	Allied	Parker	801-10	Power steering return hose	10/11/17						
Oil	Red Drum	Sinopec	15W40	Engine oil	10/11/17		3.99	4	15.96		
Latch	Bergey's	Mack	25624526	Door, left latch	10/14/17	y	6.39	2	12.78		
Control	Bergey's	Mack	25625220	Inside door latch control	10/14/17		55.16	1	55.16		
Adjustment kit	Bergey's	Mack	7313-95943	Headlight adjustment kit		y	30.79	1	30.79	114.69	10/8/17
Screws	Bergey's	Mack	25099161	Headlight trim screw	10/28/17		10.37	1	10.37		
Brakes	Bergey's	Meritor	8235-XK3124715QP	Front brake kit	10/28/17	y	1.51	1	1.51	11.88	10/22/17
Drum	Bergey's	Webb	2335-65152B	Drum, Front	11/4/17	y	64.20	2	128.40		
Slack adjuster	Bergey's	Hallex	40010011	Front slack adjuster	11/4/17	y	162.99	2	325.98		
Pin	Bergey's	Mack	745-296962N	Roll pin for knob	11/4/17	y	88.60	1	88.60	542.98	10/29/17
Bulb	F&C	NAPA	561	Dome light bulb	11/7/17	y	2.15	1	2.15		
Sensor	Bergey's	Mack	25190554	Thermocouple	11/11/17	y	1.16	1	1.16	3.31	11/5/17
Bulbs	Choice Distribution		37	Dash light bulbs	11/17/17		65.90	1	65.90		
					11/18/17	y	0.62	6	3.72	69.62	11/12/17
Pin	Bergey's	Mack	745-296962N	Roll pin for knob						2936.38	
Tarper	Detcon	Roll Right	DC400	Auto tarper	1/29/18	y	2.15	1	2.15	2.15	1/28/18
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	3/16/18		5900.00	1	5900.00	5900.00	3/11/18
Slack Adjuster	Bergey's	Hallex	40010144M1D	Rear slack adjuster	4/7/18	y	49.69	1	49.69		
Drum, Rear 7x16.5	Bergey's	Gunite	3398-3600AX /	Rear brake drum	4/7/18	y	86.53	1	86.53		
Hold down	Holtz	Holtz	M-G-6525BO	Rear hold down assembly left	4/7/18	y	84.95	1	84.95	221.17	4/1/18
Hold down	Holtz	Holtz	M-G-6526BO	Rear hold down assembly right	4/14/18		88.47	1	88.47		
Strap	Holtz	Holtz	M-G-A3306	Rear hold down, strap	4/14/18	y	88.47	1	88.47		
Contact	Bergey's	Mack	344SL13	Horn button roller contact	4/14/18	y	15.00	2	30.00	206.94	4/8/18
Filter	Bergey's	Mack	21939298	Oil filter	4/28/18	y	44.82	1	44.82	44.82	4/22/18
Filter	F&C	NAPA	7703	Oil rotor filter	5/5/18	y	7.51	2	15.02		
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	5/5/18	y	21.41	1	21.41		
Filter	F&C	NAPA	3587	Secondary fuel filter	5/5/18	y	6.50	11	71.50		
Filter	F&C	NAPA	3588	Primary fuel filter	5/5/18	y	11.92	1	11.92		
Pipe	Fazzio's		2" Pipe	Tool box mount	5/5/18	y	9.53	1	9.53	129.38	4/29/18
Cylinder	Monmouth Hose			Rebuilt lift cylinder	6/7/18		33.09	1	33.09		
Mirror	Bergey's	Velvac	708515	Mirror, 6" Spot	6/7/18	y	740.00	1	740.00	11.09	6/3/18
Pump	Bergey's	Mack	313GC5230MX	EUP	8/4/18	y	8.48	1	8.48	8.48	7/29/18
Pump	Bergey's	Mack	322GC45	Lift pump	8/23/18		508.38	1	508.38		
Steel	Fazzio's		3x7 angle 1/4 thick	Tarper pivots mounts	8/13/18	y	250.94	1	250.94	759.32	8/20/18
Cable	J C Pacific	J C Pacific	CB7/BX78B	Cable, 7/8" * 78" Button end	11/13/18		78.00	2	156.00		
					11/13/18	y	330.00	1	330.00	486.00	11/18/18

8531.35

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used Total	Total week	Week
Fitting	Choice Distribution		89103, C1862X8	1/2" Union	1/8/19	y	5.40	1	5.40	
Line	Ralph K. Badmann	Synflex	020055	1/2" Synflex	1/8/19	y	0.87	3	2.61	
Bulb	Choice Distribution		37, C28001	Light bulb	1/8/19	y	0.57	4	2.28	
Blade	F&C	NAPA	60-018, 6-018-1	Windshield wiper blade	1/8/19	y	5.99	2	11.98	
Torque rod	Bergey's	Mack	25162529	Torque rod rear to frame	1/9/19	y	302.55	1	302.55	
Torque rod	Bergey's	Mack	25170833	Torque rod, front	1/9/19	y	172.44	1	172.44	497.26 1/8/19
Fitting	Allied	Velvac	016660	3/8" Union	1/19/19	y	5.49	2	10.98	10.98 1/13/19
Fitting	Choice Distribution		89101, C1862X4	1/4" Union	1/22/19	y	3.87	1	3.87	3.87 1/20/19
Valve	Bergey's	Bendix	745-103010N	Relay valve	1/28/19	y	62.45	1	62.45	
Valve	Bergey's	Bendix	286364N	Spring brake modulating valve	1/28/19	y	126.43	1	126.43	
Valve	Bergey's	Bendix	286171N	Foot valve, E-6	1/28/19	y	88.77	1	88.77	
Fitting	Choice Distribution		C1869X10	5/8" Synflex x 1/2 NP	1/28/19	y	11.93	2	23.86	
Shive block	Detcon	Galbreath	2316W	Reeving cylinder block	1/28/19	y	175.00	1	150.00	
Cylinder	Holtz	M-G-A3147	M-G-A3147	Reeving cylinder	1/28/19	y	1650.00	1	1650.00	
Hose	Trans Bearing	Goodyear	3/4x13, 12MP, 12 O-ring	Reeving cylinder	1/28/19	y	62.89	1	62.89	
Hose	Trans Bearing	Goodyear	3/4x24, 12MP, 12 O-ring	Reeving cylinder	1/28/19	y	73.01	1	73.01	2237.41 1/27/19
Filter	Bergey's	Mack	21939298	Oil filter	2/9/19	y	6.09	2	18.18	
Filter	F&C	NAPA	7703	Oil rotor filter	2/9/19	y	21.41	1	21.41	
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	2/9/19	y	6.50	11	71.50	
Filter	F&C	NAPA	3587	Secondary fuel filter	2/9/19	y	12.37	1	12.37	
Filter	F&C	NAPA	3588	Primary fuel filter	2/9/19	y	10.00	1	10.00	
Filter	F&C	NAPA	2798	Air filter	2/9/19	y	62.52	1	62.52	47/19
Gage	Detcon	Hydra Star	3406	Slight gage	2/9/19	y	19.69	1	19.69	213.57
Valve	Bergey's	Bendix	745-103010N	Relay valve R14	2/19/19	y	62.45	1	62.45	2177/19
Valve	Bergey's	Bendix	745-800481	Relay valve, R12DC	2/19/19	y	123.42	1	123.42	185.87
Support	Bergey's	Mack	85150882	Support bar above battery box	3/13/19	y	43.51	1	43.51	43.51 3/10/19
Fuse	Choice Distribution		C28226	Fuse, mini 15A	4/15/19	y	0.42	2	0.84	0.84 4/14/19
Fitting	Choice Distribution		1862X4	1/4" Union	4/22/19	y	4.08	1	4.08	4.08 4/22/19
Steel	Fazdo		12"x12"x1	cable hook	5/20/19	y	47.96	1	47.96	47.96 5/12/19
							75.17	1	75.17	
	Bergey's	Timken	SET421	Wheel bearing, rear inner kit			29.66	1	29.66	
	F&C	National	370031A	Wheel seal, rear			53.51	1	53.51	
	Bergey's	Meritor	XK3124707QP	Shoe kit, Rear			379.99	1	379.99	
Saddle	R&H	Automann	M1116, 39QK326	Trunnion saddle 3.5"			182.85	1	182.85	
U-bolts	R&H	Automann	AUBK8394-184S	U-bolt kit, rear 1.25X4X18.5			8.25	1	8.25	727.43 5/26/19
Bolt	R&H		CB1212	Center Bolt, 1/2" x 12"						
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	6/19/19	y	53.51	1	53.51	
Seal	F&C	National	370031A	Wheel seal, rear	6/19/19	y	29.66	1	29.66	83.17
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	6/24/19	y	53.51	1	53.51	
Slack Adjuster	Bergey's	Hallex	5398-40010144	Rear slack Adjuster	6/24/19	y	90.45	1	90.45	143.96 6/23/19

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order Price	Used Total	Total week	Week
Filter	Bergey's	Mack	21939298	Oil filter	7/4/19	y				
Filter	F&C	NAPA	7703	Oil rotor filter	7/4/19	y	8.09	2	16.18	
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	7/4/19	y	22.88	1	22.88	
Filter	F&C	NAPA	3587	Secondary fuel filter	7/4/19	y	7.91	11	87.01	
Filter	F&C	NAPA	3588	Primary fuel filter	7/4/19	y	12.37	1	12.37	
Hose	Made	Parker	3/8x3', 3/BMP	Cooling hose	7/4/19	y	10.00	1	10.00	
Filter	F&C	NAPA	2798	Air filter	7/4/19	y	17.12	1	17.12	
Nut	Bergey's	Mack	8609-524	Air filter nuts	7/4/19	y	65.81	1	65.81	
Grommet	F&C	Trucklite	40700	4" Grommet	7/20/19	y	5.18	4	20.72	252.09
Grommet	Sosmetal	Trucklite	30700-3	2" Grommet	7/20/19	y	1.39	1	1.39	6/30/19
Clip	Bergey's	Mack	7313-95943	Headlight adjustment clip	7/20/19	y	2.38	1	2.38	3.77
Pipe	Bergey's	Mack	25165770	Exhaust pipe, elbow	7/29/19	y	12.55	1	12.55	7/14/19
Pipe	Bergey's	Mack	25122768	Exhaust pipe, turbo to flex	7/29/19	y	108.98	1	108.98	
Pipe	F&C	Walker	41989	Adapter, 4" to 5"	7/29/19	y	473.67	1	473.67	
Clamp	F&C	Walker	49030	4 Flex pipe	7/29/19	y	18.99	1	18.99	
Clamp	Allied	Grand Rock	FL5SS	Band clamp, 5"	7/29/19	y	15.21	4	60.84	
Solenoid	Bergey's	Donaldson	2191-X007824	Band clamp, 4" step	7/29/19	y	9.95	1	9.95	
Cab marker	Bergey's	Jake Brake	20906444	Jake brake solenoid	7/29/19	y	9.89	2	19.78	
Lamp	Ebay	Trucklite	26361Y		7/29/19	y	264.82	1	264.82	
Lamp	F&C	Trucklite	4050	4" Stop / Tail LED	8/10/19	y	89.99	1	89.99	1039.57
Pigtail	F&C	Trucklite	94902	2 Wire pigtail	8/10/19	y	16.64	1	16.64	7/28/19
Wire end	Kimball Midwest		PBSN3312	Blue butt connector 16-14	8/10/19	y	1.70	1	1.70	
Strap	Holtz	Holtz	M-G-A3306	Rear hold down, strap	8/10/19	y	0.31	3	0.93	4.24
Arm	American Roll off	Roll Right	62-702	Tarp, arm bottom half	11/5/19	y	15.00	2	30.00	8/4/19
Pin	American Roll Off	Roll Rite	62-707L	Pivot pin	11/5/19	y	323.92	1	323.92	
Breaker	Ralph K Badmann	Buss	091073	Circuit breaker, 20A, 1/4"	11/6/19	y	133.50	1	133.50	
Filter	Bergey's	Mack	21939298	Oil filter	11/9/19	y	5.95	1	5.95	493.37
Filter	F&C	NAPA	7703	Oil rotor filter	11/18/19	y	8.09	2	16.18	11/3/19
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	11/18/19	y	22.88	1	22.88	
Filter	F&C	NAPA	3587	Secondary fuel filter	11/18/19	y	7.91	11	87.01	
Filter	F&C	NAPA	3588	Primary fuel filter	11/18/19	y	12.74	1	12.74	
Filter	F&C	NAPA	2798	Air filter	11/18/19	y	10.30	1	10.30	
Lamp	F&C	NAPA	3050	2" LED marker red	11/18/19	y	65.81	1	65.81	
Seal	Bergey's	Mack	25623778	Seal, output	11/18/19	y	6.34	2	12.68	227.60
Bolt	Bergey's	Mack	25093516	Yoke bolt	11/27/19	y	28.32	1	28.32	11/17/19
Compressor	Bergey's	Sanden	RD570881P	A/C compressor	11/27/19	y	11.92	1	11.92	40.24
Belt	F&C	NAPA	25-9500	A/C belt	12/24/19	y	210.55	1	210.55	11/24/19
					12/24/19	y	18.86	1	18.86	229.41
									6490.27	
Tarp	Deroche Canvas	Deroche Canvas	Auto tarp	Auto tarp	2/17/20	y	190.00	1	190.00	190.00
Lamp	F&C	Trucklite	4050	4" Stop / Tail LED	4/13/20	y	16.64	1	16.64	2/15/20
Bearing	Bergey's	Sterco	7843-40197	Driveshaft bearing	4/15/20	y	70.59	1	70.59	
Yoke	Bergey's	Spicer	6342711	End yoke	4/15/20	y	153.38	1	153.38	
U-joint	Bergey's	Spicer	2104-5676X	U-joint	4/15/20	y	77.93	1	77.93	318.54

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order	Price	Used	Total	Total week	Week
Sensor	Bergey's	Mack	25190654	Sensor, thermocouple	5/11/20		y	76.45	1	76.45	76.45	5/10/20
Mirror	Bergey's	Mack	4999-MCK16GLS01	Mirror, glass, west coast	5/29/20	y		11.65	1	11.65	11.65	5/24/20
Filter	F&C	NAPA	3587	Secondary fuel filter	6/5/20	y		12.74	1	12.74		
Filter	F&C	NAPA	3588	Primary fuel filter	6/5/20	y		10.30	1	10.30	23.04	5/31/20
Brake	PRF Inc	PRF Inc	SCB200.500	Clutch brake	6/8/20	y		22.00	1	22.00	22.00	6/7/20
Bar	American Roll off	Roll Right	76870, 62-704	Tarp, cross bar	6/20/20		y	149.44	1	149.44	149.44	6/14/20
Clip	Bergey's	Mack	95943	Headlight adjustment clip	8/10/20	y		12.55	1	12.55		
Filter	Bergey's	Mack	21939298	Oil filter	8/13/20	y		8.44	2	16.88		
Filter	F&C	NAPA	7703	Oil rotor filter	8/13/20	y		22.88	1	22.88		
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	8/13/20	y		7.91	11	87.01		
Filter	F&C	NAPA	3587	Secondary fuel filter	8/13/20	y		12.74	1	12.74		
Filter	F&C	NAPA	3588	Primary fuel filter	8/13/20	y		10.30	1	10.30		
Filter	F&C	NAPA	2798	Air filter	8/13/20	y		62.53	1	62.53		
Pin	Bergey's	Meritor	R303715	Pin, front spring, forward eye	8/13/20	y		15.96	1	15.96		
Pin	Bergey's	Mack	25160299	Pin front lock bolt	8/13/20	y		6.56	1	6.56		
Bolt	R&H		CB1210	Center Bolt	8/13/20		y	5.36	1	5.36		
Spacer	R&H		CBL12	Center Bolt lengthener	8/13/20		y	2.50	1	2.50		
Pin	R&H		M1487	Pin, spacer dowell	8/13/20		y	10.31	1	10.31		
U-bolt	R&H		UB7830	U-bolt front	8/13/20		y	31.77	2	63.54		
Nut	R&H		DN78	U-bolt nut	8/13/20		y	2.25	4	9.00		
Washer	R&H		UBW78	U-bolt washer	8/13/20		y	1.65	4	6.60	344.72	8/9/20
Hose	Allied	Mack	25133923	After cooler hose	9/10/20		y	30.85	1	30.85		
Clamp	Allied	Mack	20705898	Hose clamp	9/10/20		y	21.00	1	21.00	51.85	9/6/20
Solenoid	Granger	Ingersoll Randd	2F983	Rear hold down air solenoid	10/28/20		y	115.23	1	115.23		
Hold down kit	Holtz	Galfab	M-G-A4285	Rear hold down air kit	10/28/20		y	1499.00	1	1499.00		
Hose	F&C	Hallex	16330	Rear hold down air hook up	10/28/20		y	10.41	2	20.82		
Fitting	Kimball		90756	3/8 Bulk head pipe F	10/28/20		y	17.37	2	34.54	1869.59	10/25/20
Filter	2LC3	McNeilus	1108713	Hydraulic filter	11/14/20	y		11.47	1	11.47	11.47	11/8/20
Steel	Fazzio		3x3x1/2, 10'	Hookers guard	11/27/20		y	49.94	2	99.88	99.88	11/22/20
											2968.63	
Switch	Bergey's	Vehicle Safety	915Y703	Switch, Turn single, hi-low	4/5/21	y		34.85	1	34.85		
Lamp	F&C	Grote	G3002	2" LED marker red	4/5/21	y		9.70	1	9.70		
Weather stripping	Bergey's	Mack	26155441	Roll up window, sides	4/10/21	y		5.70	2	11.40	55.95	4/4/21

Part	Vender	OEM	Part #	Description	Date of installation	From stock	Order	Price	Used	Total	Total week	Week
Bolt	R&H		UB7828	U-bolt, front	5/19/21							
Washer	R&H		UBW78	U-bolt washer	5/19/21							
Nut	R&H		DN78	U-bolt nut	5/19/21			59.86	2	119.72		
Bolt	R&H		CB1210	Center Bolt	5/19/21			1.65	4	6.60		
Pin	R&H		M1487	Pin, spacer dowel	5/19/21			2.25	4	9.00		
Spacer	Mercer Spring		ME-16967	Spring spacer	5/19/21			5.36	1	5.36		
Shock	F&C	NAPA, Monroe	65411	Shock, front	5/19/21			10.31	1	10.31		
Fender	Bergey's	Mack	25498687	Fender extension, right	5/19/21			53.99	1	53.99		
Support	Bergey's	Mack	85150882	Fender extension support	5/19/21			82.61	2	125.22		
Stud	Bergey's	Mack	85150884	Fender extension support	5/19/21			113.71	1	113.71		
Nut	Allied	Gunite	W1403	Wheel studs	5/19/21			47.39	1	47.39		
Cap	Bergey's	Meritor	R006000APL	Lug nut	5/19/21			135.94	1	135.94		
	Bergey's	SKF	1458-1691	Hub cap	5/19/21			10.61	1	10.61		
Clutch	F&C	D&W	EZN10893551	Clutch	5/19/21			2.02	1	2.02		
Bearing	F&C	SKF	6306-22NRJ	Pilot bearing	5/31/21			36.75	1	36.75	676.62	5/16/21
Hose	Made	Parker	3/4x6", 16MJIC 16FJIC	Rear hoist hoses	5/31/21			620.99	1	620.99		
Bolt	Bergey's	Mack	25167041	U-bolt, front	6/30/21			47.44	1	47.44	668.43	5/30/21
Nut	Bergey's	Mack	25098611	U-bolt nut	7/3/21			45.52	2	91.04		
Washer	Bergey's	Mack	25088023	U-bolt washer	7/3/21			40.28	2	80.56		
Nut	R&H		DN12	Center bolt nut, 1/2"	7/3/21			6.79	4	27.16		
Bolt	R&H		CB126	Center Bolt	7/3/21			7.24	4	28.96		
Roller	Holtz	Holtz	M-G-2354W.ASSY	Rear ground roller	7/3/21			1.55	1	1.55		
S-cam	Bergey's	Meritor	2210K7421	S-Cam, right rear	7/9/21			2.63	1	2.63	231.90	6/27/21
Seal	F&C	National	370031A	Wheel seal, rear	7/10/21			151.00	1	151.00	151.00	7/4/21
Adjuster	Bergey's	Hallex	40010144	Slack Adjuster	7/10/21			55.95	1	55.95		
Brake can	Bergey's	Road Choice	SB3030STD	Rear Can, 30/30	7/10/21			29.08	1	29.08		
Filter	Bergey's	Mack	21939298	Oil filter	7/12/21			90.45	1	90.45	175.48	7/4/21
Filter	F&C	NAPA	7703	Oil rotor filter	7/17/21			37.50	1	37.50		
Oil	Petro Choice	Dyna Plex	15W40	Engine oil	7/17/21			8.49	2	16.98		
Filter	F&C	NAPA	3587	Secondary fuel filter	7/17/21			22.87	1	22.87		
Filter	F&C	NAPA	3588	Primary fuel filter	7/17/21			9.53	11	104.83		
Brake can	Bergey's	Road Choice	SB3030STD	Rear Can, 30/30	7/17/21			12.66	1	12.66		
Brakes	Bergey's	Meritor	XK3124707QP	Rear brake kit	7/17/21			10.40	1	10.40		
Shock absorber	Bergey's	National Sealing	6222082001	Seat shock absorber	7/17/21			37.50	1	37.50		
Adjuster	Bergey's	Mack	7313-95943	Headlight adjustment assembly	8/21/21			59.19	1	59.19	296.25	7/11/21
Pump	Bergey's	Mack	316GC551M3X	Water pump	8/24/21			29.47	1	29.47	29.47	8/15/21
					9/1/21			13.68	1	13.68	13.68	8/22/21
								371.55	1	371.55	371.55	8/29/21

2670.33

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
2" LED marker red	F&C	Trucklite	3050	1	y	6.34	6.34	6.34	10/8/21
Hose, Suction	Trans Bearing		2"	8.5	y	14.78	125.63		
Driveshaft bearing mount	Bergey's	Mack	25160106	1	n	81.59	81.59		
Driveshaft bearing	Bergey's	Meritor	GAFF40074	1	y	81.40	81.4		
Rear hold down air cylinder	Ebay	Numatics	2500D02-03A-20	1	n	162.28	162.28	450.90	10/16/21
Shift stick	Bergey's	Mack	25125889	1	n	337.78	337.78	337.87	10/20/21
Trunnion thrust washer, bronze 3 1/2"	Bergey's	Meritor	R303698	1	y	14.39	14.39	10.39	10/30/21
Fuel cap 3" Vented	Bergey's	Mack	25195379	1	y	51.10	51.10	51.10	12/15/21
Shoe kit, Front	Bergey's	Meritor	XK3124715QP	2	y	67.04	134.08		
Oil filter	Bergey's	Mack	21939298	2	y	8.49	16.98		
Oil filter, Rotor kit	F&C	NAPA	7703	1	y	22.87	22.87		
Engine oil	Petro Choice	Dyna Plex 21C	15W40	11	y	10.83	119.13		
Primary fuel filter	F&C	NAPA	3588	1	y	11.11	11.11		
Secondary fuel filter	F&C	NAPA	3587	1	y	13.51	13.51		
Air filter	F&C	NAPA	2798	1	n	62.53	62.53	380.21	12/18/21
Door hinge	Bergey's	Mack	25120138	1	n	139.58	139.58	139.58	12/28/21
							2021 total	4046.72	
2" Grommet	F&C	Trucklite	30700	2	y	1.65	3.30	3.30	2/11/22
Exhaust pipe, elbow 37	Bergey's	Mack	25165770	1	y	115.29	115.29		
Exhaust pipe, Y	Big Chrome Shop		HD-14C-500A	1	n	129.99	129.99		
Adapter, 4" to 5" ID	Big Chrome Shop		GR-R5I-4IA	1	n	33.99	33.99		
Band clamp, 5" step	F&C	NAPA	733-3225	1	y	12.99	12.99	292.26	2/19/22
Side roller, 3"	Holtz	Holtz	M-G-521-AO	3	y	27.00	81.00		
Side roller cotter pin	Holtz	Holtz	M-G-1525	4	y	0.59	2.36	83.36	3/1/22
Side roller, 4"	Holtz	Holtz	M-G-522-AO	1	y	40.00	40.00		
Side roller pin, 4"	Holtz	Holtz	M-G-1746W	1	y	24.35	24.35		
Washer for roller	Holtz	Holtz	M-G-552-W	1	y	0.99	0.99		
Side roller cotter pin	Holtz	Holtz	M-G-1525	1	y	0.59	0.59	65.93	3/5/22

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
Light bulb	Kimball Midwest	CEC	1156, 28071	1	y	0.77	0.77	0.77	3/7/22
Shoe kit, Rear	Bergey's	Meritor	XK3124707QP	1	y	71.22	71.22		
S-Cam, right, rear	Allied	Euclid	E9650	1	n	43.99	43.99		
S-Cam bushing kit	Allied	Euclid	E3993B	1	n	11.50	11.50		
Wheel seal, rear	F&C	National	370031A	1	y	31.92	31.92	158.63	3/15/22
Headlight adjustment clip	Bergey's	Mack	7313-95943	1	y	13.20	13.20		
Rear yoke front of front	Mr. Driveshaft	Spicer	6.5-4-4271-1X	1	n	405.00	405.00		
Pinion seal, Rear of front rear	Bergey's	National	23396652	1	n	18.34	18.34		
Pinion seal, rear carrier	Bergey's	National	25624339	1	y	17.85	17.85	454.39	4/19/22
Driveshaft bearing mount, front	Bergey's	Mack	25160106	1	n	87.85	87.85	87.85	4/26/22
Battery	Bergey's	Exide	PX31925C	2	y	80.70	161.40	161.40	6/6/22
Thermostat	Bergey's	Red Dot	4379-RD442724P	1	y	26.68	26.68		
Hose, general purpose, 1	Allied	Parker	801-16	1	y	5.00	5.00	31.68	6/25/22
Oil filter	Bergey's	Mack	21939298	2	y	8.57	17.14		
Oil filter, Rotor kit	F&C	NAPA	7703	1	y	27.64	27.64		
Engine oil	Petro Choice	Dyna Plex 21C	15W40	11	y	11.63	127.93		
Primary fuel filter	F&C	NAPA	3588	1	y	12.59	12.59		
Secondary fuel filter	F&C	NAPA	3587	1	y	15.30	15.30		
Air filter	F&C	NAPA	2798	1	n	80.12	80.12		
Air filter nuts	Bergey's	Mack	8609-524	2	y	5.18	10.36	291.08	7/11/22
Shoe kit, Rear	Bergey's	Meritor	XK3124707QP	1	y	75.65	75.65		
Wheel seal, rear	F&C	National	370031A >	1	y	31.92	31.92	107.57	7/16/22
S-Cam, left, rear	Allied	Euclid	E9659	1	y	42.95	42.95		
S-Cam bracket, left front rear	Bergey's	Meritor	A3211M5629	1	n	193.59	193.59		
Shoe kit, Rear	Bergey's	Meritor	XK3124707QP	1	y	75.65	75.65		
Drum, Rear 7x16.5	Bergey's	Gunite	3600AX	1	y	165.88	165.88	478.07	9/7/22
Slack Adjuster	Bergey's	Hallex	40010011	1	y	97.95	97.95		
Hub cap	Bergey's	SKF	1691	1	y	38.94	38.94	136.89	10/19/22
3 Wire pigtail	F&C	Grote	67000	1	y	4.29	4.29	4.29	11/16/22
2" LED marker red	F&C	Trucklite	3050	1	y	6.64	6.64	6.64	12/23/22

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
Windshield wiper arm LH	Bergey's	Mack	25109820	1	n	57.19	57.19	57.19	
Windshield wiper blade 18"	F&C	NAPA	6-018-1	1	y	8.45	8.45	8.45	12/28/22
Tarp, elbow	Holtz	Roll Right	ROLL-76800	1	y	80.57	80.57	80.57	12/29/22
							2022 total		
							2510.32		
2 1/2" Beehive amber	F&C	Trucklite	1075AD	1	y	11.99	11.99	11.99	1/11/23
Clutch brake		Haldex	BK313	1	n	27.75	27.75		
Pilot bearing	Camarota	DT Components	306VVL	1	n	37.98	37.98		
Clutch 1850 Ft Lbs.	Camarota	Eaton	308925-98	1	n	1363.74	1363.74		
Transmission, rebuilt ex	Camarota	Mack	MT308	1	n	6140.65	6140.65		
Band clamp, 4" step	Bergey's	Donaldson	2191-X007824	2	y	12.95	25.90		
Exhaust pipe, turbo flange 5"	Allied	Automann	562.U1588A	1	n	21.95	21.95		
Clutch shaft	Camarota	PAI	6136	1	n	42.25	42.25		
Clutch shaft	Camarota	PAI	6134	1	n	104.91	104.91	7785.14	2/16/23
Oil filter	Bergey's	Mack	21939298	2	y	8.49	16.98		
Oil filter, Rotor kit	F&C	NAPA	7703	1	y	29.30	29.30		
Engine oil	Petro Choice	Dyna Plex 21C	15W40	11	y	14.33	157.63		
Primary fuel filter	F&C	NAPA	3588	1	y	13.34	13.34		
Secondary fuel filter	F&C	NAPA	3587	1	y	16.22	16.22		
Air filter	F&C	NAPA	2798	1	n	80.12	80.12	313.59	3/4/23
4" Stop / Tail LED	F&C	Trucklite	4050	1	y	18.16	18.16	18.16	3/11/23
Switch, rocket, 2 tabs	Bergey's	Mack	25164287	1	y	19.23	19.23	19.23	3/15/23
Parking brake valve PP-1	F&C	Haldex	276567X	1	y	28.86	28.86	28.86	3/21/23
Radiator cap 10lbs	Bergey's	Mack	16MF264, 25005579	1	n	14.49	14.49		
Expansion tank cap	Bergey's	Mack	3150-063415A	1	n	18.88	18.88	33.37	3/27/23
Tarp	Deroche Canvas	Deroche Canvas	8 X 28	1	y	111.00	211.00	253.01	4/1/23
Tarp flange kit	Holtz	Roll Right	76810	1	y	39.01	39.01	38.94	4/1/23
Hub cap	Bergey's	SKF	1458-1691	1	y	38.94	38.94	38.94	4/1/23
Hood hinge eye	Bergey's	Mack	25087088	1	y	93.76	93.76	93.76	6/10/23

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
Motor mount, front bushing	Bergey's	Mack	25164179	4	y				
Motor mount, front bolt	Bergey's	Mack	25095339	2	y	8.71	34.84		
Motor mount, front nut	Bergey's	Mack	25089732	2	y	24.17	48.34		
Motor mount, front spacer	Bergey's	Mack	25626139	2	y	8.05	16.10		
Radiator	Allied	Automann	811.62102	1	n	16.36	32.72		
Hose clamp, T style 4.5"	Allied	Velvac	022586	2	y	650.00	650.00		
Tarp, elbow 90	Holtz	Roll Right	ROLL-76800	1	y	17.55	35.10	817.10	6/30/23
Steel channel	Fazzio		6.x8.2 x 5'	1	n	80.57	80.57	80.15	7/21/23
Steel tube	Fazzio		3x3x1/316	1	n	42.6	42.60		
Steel pipe	Fazzio		3" sec 40 x 5	1	n	53.83	53.83		
Steel plate	Fazzio		1/2 x 4 x 4	1	n	51.94	51.94		
Tarp pivot pin, right	American Roll off	Roll Right	62-707R	1	y	228.85	228.85		
Tarp, arm bottom half	American Roll off	Roll Right	62-702	2	n	133.50	133.50		
Tarp, arm	Holtz	Roll Right	ROLL-46220	1	n	384.85	769.70		
Fenders	Detcon		R-F-2001	2	n	246.10	246.10		
Oil filter	Bergey's	Mack	21939298	2	y			1526.52	7/27/23
Oil filter, Rotor kit	Bergey's	Mack	21074769	1	n	8.49	16.98		
Engine oil	Petro Choice	Dyna Plex 21C	15W40	11	y	108.11	108.11		
Primary fuel filter	F&C	NAPA	3588	1	y	13.98	153.78		
Secondary fuel filter	F&C	NAPA	3587	1	y	13.34	13.34		
Parking brake valve PP-1	F&C	Haldex	276567X	1	y	16.22	16.22	308.43	9/4/23
Knob and pin, PP-1	Bergey's	Bendix	108235N	1	y	29.51	29.51		
4" Stop / Tail LED	F&C	Trucklite	4050	1	y	19.60	19.60		
Rear yoke, front of rear	Bergey's	Meritor	17TYS3260A	1	y	18.65	18.65	67.76	9/15/23
U-joint strap kit	Bergey's	Spicer	6.5-70-18X	2	y	135.52	135.52		
Shoe kit, Rear	Bergey's	Meritor	XK3124707QP	2	y	10.24	20.48		
Drum, Rear 7x16.5	Allied	Automann	151.6700BATR	2	y	70.01	140.02		
Wheel seal, rear	F&C	National	370031A	2	y	149.00	298.00	657.86	10/10/23
Sun visor clip	Bergey's	Mack	25157939	1	n	31.92	63.84		
Back up switch	Bergey's	Pollak	25157099	1	n	6.70	6.70	6.70	10/26/23
Work Light Assembly	F&C	Trucklite	80360	1	y	46.64	46.64	46.64	10/28/23
						15.95	15.95	15.95	11/2/23

Description	Vendor	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
Work Light	Tractor Supply		1169558	1	n	39.99	39.99		
Valve handle boot round	Holtz	Holtz	M-G-A3760	2	y	9.95	19.90	59.89	11/18/23
Rear hold down air cylinder	Holtz	Numatics	M-G-A4716	1	y	196.25	196.25	196.25	11/29/23
Mirror, 6" Fender		Mirror Tech	207-6	1	y	28.50	28.50		
Fuel cap 3" Vented	Bergey's	Mack	25195379	1	y	67.61	67.61	96.11	12/2/23
2" LED marker red	F&C	Trucklite	3050	1	y	6.82	6.82	6.82	12/7/23
							760.14	2023 Total	
								12459.23	
Boot, after cooler	Bergey's	Volvo	8178232	1	y	72.00	72.00		
Hose clamp #48, silicone	Kimball Midwest	Breeze	502648	2	y	2.73	5.46		
Hose clamp #10 silicone	Kimball Midwest	Breeze	502610	2	y	1.70	3.40	80.86	1/5/24
Air Dryer AD-9, rebuilt	F&C	Haldex	109685X	1	n	135.15	135.15		
Door, left control lock inside	Bergey's	Mack	25625220	1	n	47.00	47.00	182.15	1/16/24
Seat, driver	Bergey's	Mack	800-2339131546	1	n	760.14	760.14		
Windshield washer bottle cap	Bergey's	Mack	25171665	1	n	8.37	8.37	768.11	2/24/24
Headlight assembly	Bergey's	Mack	21077000	1	n	137.86	137.86	137.86	3/4/24
Windshield wiper blade 18"	F&C	NAPA	6-018-1	1	y	10.69	10.69	10.69	3/28/24
Drum	Bergey's	Gunit	3600AX	2	n	156.99	313.98		
Shoe kit, Rear r	Bergey's	Meritor	XK3124707QP	2	n	74.32	148.64		
Wheel seal, rear	Bergey's	Stemco	7843-3930104	2	n	45.85	91.70		
S-Cam bushing kit	Bergey's	Meritor	KIT8042	1	n	9.71	9.71		
S-Cam	Bergey's	Meritor	2210H7522	1	n	53.41	53.41		
S-Cam, left	Bergey's	Meritor	2210L7422	1	n	69.55	69.55		
Slack Adjuster	Bergey's	Haldex	40010144	1	n	113.24	113.24		
Slack Adjuster	Allied	Automann	135.2832	1	n	55.88	55.88	856.11	4/1/24
Exhaust pipe, turbo to flex	Bergey's	Mack	25153474	1	n	358.44	358.44		
Clamp, Turbo	Bergey's	Mack	25114573	1	n	45.04	45.04		
Exhaust pipe	Bergey's	Mack	25156115	1	n	151.96	151.96		
Clamp	Bergey's	Mack	8181264	1	n	6.75	6.75		
Band clamp, 4" step	Bergey's	Donaldson	X007824	2	n	13.75	27.50		
Clamp	Bergey's	Mack	25165870	1	n	47.29	47.29	636.98	4/19/24

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
U-joint strap kit	Allied	Spicer	752.657018X	4	n	16.98	67.92		
Clutch brake	F&C	Haldex	BK313	1	n	26.75	26.75	94.67	4/29/24
2 1/2" Beehive amber	Bergey's	Trucklite	10276Y	1	n	21.68	21.68		
Cab marker	Bergey's	Trucklite	25130491	1	n	134.48	134.48	156.16	5/3/24
Rear hold down air cylinder	Holtz	Numatics	M-G-A4716	1	y	196.25	196.25	196.25	5/7/24
Rear hold down air cylinder	Holtz	Numatics	M-G-A4716	1	n	196.25	196.25	196.25	5/20/24
Battery	F&C	NAPA	7236	3	y	91.89	275.67		
Oil filter	F&C	NAPA	1791	2	y	11.66	23.32		
Oil filter, Rotor kit	F&C	NAPA	7703	1	y	30.07	30.07		
Engine oil	Petro Choice	Dyna Plex 21C	15W40	11	y	13.98	153.78		
Primary fuel filter	F&C	NAPA	3588	1	y	13.45	13.45		
Secondary fuel filter	F&C	NAPA	3587	1	y	17.08	17.08		
Air filter	F&C	NAPA	2798	1	y	79.05	79.05	592.42	6/17/24
Back up, bolt on	F&C	Ecco	7301067	1	y	40.40	40.40	40.40	6/20/24
Switch, Revers	Bergey's	Pollak	25157099	1	n	47.54	47.54	47.54	7/15/24
Valve seal kit, VA35	McNeilus	McNeilus	0614153	2	y	17.11	34.22		
Steering shaft, U-joint	Bergey's	Spicer	2104-5103X	2	y	20.94	41.88		
Steering shaft bearing	Bergey's	Mack	25107551	1	n	136.59	136.59	212.69	8/3/24
Fuel lift pump	Bergey's	Mack	85013282	1	n	357.24	357.24		
Fuel filter housing	Bergey's	Mack	32GB515M	1	n	164.11	164.11	521.35	8/13/24
4" Revers LED	F&C	NAPA	4060C	2	y	52.97	105.94		
Junction box	F&C	Trucklite	15-961	1	n	24.08	24.08	130.02	8/26/24
Cable, 7/8" * 82' Button end	J C Pacific	J C Pacific	CB7/8X82B	1	y	555.00	555.00	555.00	10/16/24
Oil filter	F&C	NAPA	1791	2	y	11.66	23.32		
Oil filter, Rotor kit	F&C	NAPA	7703	1	y	30.07	30.07		
Engine oil	PPC Lubricants	Shell Rotella	15W40	11	y	13.13	144.43		
Primary fuel filter	F&C	NAPA	3588	1	y	13.45	13.45		
Secondary fuel filter	F&C	NAPA	3587	1	y	17.08	17.08		
Air filter	F&C	NAPA	2798	1	y	79.05	79.05	307.40	11/27/24

Description	Vender	OEM	Part #	Used	From Stock	Price	Total	Total job cost	Date
2" Marker LED amber	F&C	Trucklite	3050A	1	y	6.82	6.82	6.62 956.41	12/9/24
								2024 Total 6686.34	
2" LED marker red	F&C	Trucklite	3050	1	y	7.43	7.43	7.43	2/12/25
Rebuilt driveshaft	Mr.Driveshaft			1	n	956.41	956.41		
U-joint strap kit	Allied	SKF	UJ476-10	2	Y	11.95	23.90	980.31	2/25/25
								Yearly Total 987.74	



Allied Diesel Service Inc.
869 Hwy 33 East
Freehold, NJ 07728
Phone: 732-462-5072 Fax: 732-409-1072
www.allieddieselservice.com

INVOICE

89161

NJ emissions PIF#000727

INVOICE

Vehicle Received: 05/17/2016

Invoice Date: 06/14/2016

Dellsa Demolition Inc
101 Commerce Drive
Tinton Falls, NJ 07753
Office: 732-988-2525 Fax: 732-988-8333
Cust ID: 129

2004 Mack - RD690S -
Lic #: XB-592Y - NJ
Unit #: 88
VIN #: 1M2P337C5 4M034632

Odometer In: 337332

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extended
Sensor 20706327	1.00	45.27	45.27	Check For Engine Noise Or Fuel Knock	64.00	6720.00
Remack Oil/Haul Kit 215SB285AX	1.00	5280.78	5280.78	Brought truck inside shop to troubleshoot issue. Sounded like noise was coming from rear of engine. Connected to Mack ET program to perform cylinder balance test and try to isolate cylinder. Could not perform any tests through laptop. Found out reason was a defective speed sensor in flywheel housing. Also noticed mounting bolt for speed sensor is broken off in flywheel housing. Had to remove clutch linkage to access broken bolt. Drilled out, weld extension piece to broken bolt and extract out broken bolt. Rechase threads for new mounting bolt. Installed new speed sensor in flywheel housing, reconnected harness to sensor, secured with new mounting bolt and reinstalled clutch linkage. Next performed cylinder balance test and found #5 cylinder and #1 cylinder failed test. Removed air crossover and charged air piping for access to remove valve covers. Removed both valve covers and found #1 cylinder injector was faulty but found major issue with #5 cylinder. Found #5 intake valve had failed, was coming apart and was higher than all other valves. At this point will have to pull cylinder heads. Drained engine coolant and disconnected batteries. Put front passenger side axle on jack stand and removed wheel for better access. Remove turbocharger, rear exhaust bracket, exhaust manifolds, intake manifold, thermostat housing, both rocker housing assemblies and all fuel, coolant and oil lines to both cylinder heads for access. Removed both cylinder heads and inspected internal engine parts. Found two cylinders with scored cylinder walls and damage to cylinder heads from material of #5 intake valve. Pieces of damaged intake valve goes through intake and gets trapped between engine valves and valve seats throughout all cylinders. Also pieces of damaged intake valve went through turbocharger damaging turbine. Advised customer and decision was made to overhaul engine with new engine bearings, cylinder packs with liners, connecting rods, injectors, turbocharger and rebuilt cylinder heads. Exhaust manifolds are warped, in poor shape, continuously blowing out exhaust manifold gaskets and will need to be replaced also. Drained engine oil and removed oil pan. Removed all pistons, connecting rods and cylinder liners from engine. Cleaned deck on cylinder block, intake manifold and oil pan. Blew air through intake side of air compressor lines to remove debris from getting into and damaging air compressor. Installed new pistons, piston rings and liners. Installed new connecting rods with new rod and main bearings. Installed rebuilt oil pump assembly. Installed new thrust washers then reinstalled oil pan with new pan gasket. Groomed new cylinder heads with parts from old cylinder heads as needed. Installed new cylinder heads with new head gaskets and torque cylinder heads to spec. Installed all rebuilt injectors. Reinstalled all rocker arm shafts, rocker arms, bridges and all engine brake parts. Connected wires to engine brake parts as needed and adjusted all valves and injectors to spec. Reinstalled all fuel, coolant and oil lines to both cylinder heads. Installed new three-piece exhaust manifolds with new gaskets. Installed new turbocharger mounting studs and installed rebuilt turbocharger with new gaskets and seal rings. Reconnected oil lines to turbocharger and reinstalled rear exhaust bracket. Reinstalled intake manifold with new gaskets.		
Reman Cyl Head 732GB3499MX	2.00	1168.09	2336.18			
Remack Aset-IEGR Injectors 736GB414M2X	6.00	210.92	1265.52			
Reman Oil Pump 315GC466MX	1.00	655.49	655.49			
Center Exhaust Manifold 104GC5213AM	1.00	312.66	312.66			
End Exhaust Manifold 104GC5203AM	2.00	369.23	738.46			
Exhaust Manifold Kit UEMET2KIT	1.00	149.98	149.98			
Filter Kit 215SB325A	1.00	95.43	95.43			
Thermostat Kit 215SB165CP3	1.00	67.79	67.79			
Reman Turbo #170-070-0041 631gc5172m5	1.00	1796.63	1796.63			
Constant Torque Clamp 022425	1.00	11.95	11.95			
T Bolt Clamp 022584	1.00	16.50	16.50			
Hose Clamp 5216	4.00	2.74	10.96			
Parker Pushlok Hose Size: 1 801-16	2.00	10.99	21.98			
Stud 616GC228M	4.00	17.50	70.00			
Preformed Exhaust Clamp PF-4SS	1.00	15.57	15.57			
Brake Clean 2417	2.00	4.95	9.90			
Cast Iron Paint DE1651	3.00	9.75	29.25			
Rotella 15w40 Oil Bulk 500004741	44.00	4.51	198.44			
ELC Coolant 50/50 Size: GALLON 9404206021	7.00	18.95	132.65			

Written By: Darlenzo, Ralph - Technicians: Please Select, Technician: Cadigan, Keith

Page 1 of 2

Copyright (c) 2016 Mitchell Repair Information Company, LLC invhrs 7.2.15d

**Allied Diesel Service Inc.**

869 Hwy 33 East
Freehold, NJ, 07728
Phone: 732-462-5072 Fax: 732-409-1072
www.allieddieselservice.com

INVOICE

89161

NJ emissions PIF#00072

INVOICE

Vehicle Received: 05/17/2016

Invoice Date: 06/14/20

Delisa Demolition Inc

101 Commerce Drive

Tinton Falls, NJ 07753

Office: 732-988-2525 Fax: 732-988-8333

Cust ID: 129

2004 Mack - RD690S -

Lic #: XB-592Y - NJ

Unit #: 88

VIN #: 1M2P337C5 4M034632

Odometer In: 33733

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	Extende
Shop Supplies			19.00	Reinstalled thermostat housing with new gaskets and new thermostat assembly. Installed new fuel and coolant seal rings, grommets and O-rings as needed. Installed new fuel filters, oil filters and coolant filter. Installed new exhaust seal clamp for turbocharger downpipe. Installed new coolant surge tank fill hose with new clamp for old one was in poor shape. Also installed new hose clamps as needed. Reinstalled valve covers with new valve cover grommets and new valve cover gaskets. Installed new antifreeze coolant and new engine oil. Reinstalled air crossover and charged air piping with new spring loaded charged air clamps. Reconnected batteries, painted engine, bled air from fuel system and coolant system.		
				Continued text:	0.00	
				Primed fuel system, started engine and let run a while to build engine temperature. Checked for leaks, topped off coolant and oil, reinstalled front passenger side wheel and took right front off jack stand. Brought truck over to wash bay and pressure washed off engine. Connected to Mack ET program, cleared all fault codes and road tested to make sure engine is running properly.		
				Computer Diagnostics	1.00	125.00

[Payments -]

Labor:	6,845.00
Parts:	13,280.30
Sub:	20,125.30
Tax:	506.40
Total:	\$20,631.70
Bal Due:	\$20,631.70

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Signature

Date

Time

Written By: Darinzo, Ralph - Technicians: Please Select, Technician: Cadigan, Keith

Page 2 of 2

Copyright (c) 2016 Mitchell Repair Information Company, LLC Invois 7.2.1



Allied Diesel Service Inc.
869 Hwy 33 East
Freehold, NJ. 07728
Phone: 732-462-5072 Fax: 732-409-1072
www.allieddieselservice.com

INVOICE

89780

NJ emissions PIF#0007

Printed: 07/27/20

INVOICE

Delisa Demolition Inc #129
101 Commerce Drive
Tinton Falls, NJ 07753
Office: 732-988-2525 Fax: 732-988-8333

2004 Mack - RD690S -

Lic #: XB-592Y - NJ

Unit #: 88

VIN #: 1M2P337C5 4M034632

Odometer In: 339925

Part Description / Number	Qty	Sale	Ext	Labor Description	Hours	E
Solenoid 805GC548	1.00	244.90	244.90	1) Check For Slight Engine Miss Intermittently	5.00	525.00
Sensor 20706228	1.00	158.14	158.14	2) Engine Brake Not Working		
Sensor 20706327	1.00	53.04	53.04	Checked battery connections and road tested to verify customer complaint. Noticed check engine light came on and then went out a few times on road test. Brought truck inside shop and connected to Mack ET program to check for fault codes. Noticed fault codes for timing/top dead center (TDC) out of range and intake manifold boost pressure above or below normal limits. Checked engine harnesses and electrical grounds for possible shorts creating fault codes. Checked timing sensor located in engine front cover and found faulty. Removed faulty timing sensor, installed new timing sensor and reconnected sensor harness. Checked boost sensor in intake manifold on drivers side and also found faulty. Removed faulty boost sensor, installed new boost sensor and reconnected sensor harness. Troubleshoot engine brake not working. Removed charged air pipe for access to valve covers. Removed both valve covers and checked both engine brake controls solenoids. Found front engine brake control solenoid defective hanging open. Removed defective solenoid, installed new front engine brake control solenoid and reconnected wires to solenoid. Started engine, checked operation of engine brake and engine brake now working. Reinstalled both valve covers and charged air pipe. Cleared all fault codes, road tested and everything okay.		
Shop Supplies			9.81			

PAID
9-12-16
CK#7655
\$2,566.79

[Payments -]

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose of testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	525.00
Parts:	465.80
Sub:	990.80
Tax:	37.40
Total:	\$1,028.30
Bal Due:	\$1,028.30

Vehicle Received: 8/28/2016

Signature _____

Written By: Darianzo, Ralph - Technicians Please Select Technician: Lanz, Wes; Ca

Page 1 of 1

Date _____

Time _____

Copyright (c) 2016 Mitchell Repair Information Company, LLC Invt# 04.12.16

**SPRING & TRUCK REPAIR**

Your Auto, Truck & Trailer
Suspension and Alignment Specialists


Fax: (732) 681-5887
Phone: (732) 681-9000
4806 W. Hurley Pond Rd.
Wall, NJ 07719
www.rhspring.com

SERVICE INVOICE

Date	Invoice #
5/23/2022	67896

Visit us at WWW.RNHSpring.com**BILL TO**

Delisa Demolition Inc.
101 Commerce Dr.
Tinton Falls, NJ 07753
Phone: (732) 988-2525
Joe cell (908)415-1456



State Tax ID/Phone#

ST4/223634028
mtsl@optonline.net
OK
Fax: (732) 988-8333

CC Code

Vehicle/Trlr/Parts	P.O. No.	Payment Terms	Mileage	Due Date	Plate #	Vehicle #
2004 Mack RD690S			29,129	5/23/2022		88

Qty	Item	Description	U/M	List	Rate	Amount
		Rebush Rear as Needed			460.34	460.34
1	RE52R	Reconditioned/Repaired Rear Spring, Mack	Ea.		6.25	6.25
1	CB1212	Spring Center Bolt 1/2" Dia. X 12" Long	Ea.		2.50	2.50
1	CB12	Center Bolt Lenthener 1/2" I.D. X 3/4" O.D. X 3/16" High	Ea.		0.88	0.88
1	LW	Lock Washers	Ea.		1.15	1.15
1	DN12	Deep Nut 1/2" I.D.	Ea.		190.20	380.40
2	AUBK8394-194S	Mack UBolt Kit, 1.25X4X19.5	Per Kit		279.64	559.28
2	M1115	Mack Trunnion/3 1/2" Bushing 4"	Ea.			
		Spring//Mack#39QK326/39QK27E/39QK27F			67.68	135.36
2	97534	Mack/Trunnion Grease Cap	Ea.			
		(Cast)Auto#M1158/Flagg#E456-62/Dayton#334-468			60.50	121.00
2	97536	Mack/Spindle Nut Assy./Auto#M1600/Flagg#E677-62/Dayton#334-441	Ea.		13.75	27.50
2	97538	Mack/Nut Lock Washer/Auto#MX305/Flagg#MCK4/Dayton#334-442	Ea.		32.06	128.24
4	97539	Mack/Bronze Thrust	Ea.			
		Washer/Auto#MX302/Flagg#MCK1/Dayton#334-443			44.15	88.30
2	97541	Mack/Steel Space Washer 3.5" Center	Ea.			
		Hole/Auto#MX303/Flagg#MCK2/Dayton#334-444			22.16	44.32
2	97542	Mack/Grease Seal/Auto#MX301/Flagg#MCK6/Dayton#334-445	Ea.		137.10	548.40
4	97594UB	Urethane Spring Insulator Bushing, Lower, Mack	Ea.		50.13	200.52
4	97595	TALL PROFILE Mack/Upper Insulator Pad Pin Dia. 1 3/4" 4 1/2" X 6" X 3" Thick/Auto#ABP4/Flagg#MP4/Dayton#325-113	Ea.			
1	GAU06520	Stanton, Mack, Square Pattern, Non Removable Trunnion Bar	Ea.		4,288.56	4,288.56
1	GAU998-5023	Reamer, 1 1/16 1/2" Shank	Ea.		185.00	185.00
1	SHIPPING	Shipping Charges			278.47	278.47
2	CS383	Cap Screw 3/8" Dia. X 3" Long Coarse Thread Grade 8	Ea.		1.77	3.54
2	SN38	Stop Nut 3/8" Dia. (Stover Type GRADE C)Coarse Thread	Ea.		1.12	2.24
4	FW38	Flat washer 3/8"	Ea.		1.09	4.36
	SS161	Cap Screw 5/16" Dia. X 1" Long Coarse Thread Grade 8	Ea.		0.74	1.48
	GF18ST	Grease Fitting, Zerk 1/8 Pipe, Straight	Ea.		0.57	2.28
2	CS59-12	Cap Screw 5/8" Dia. X 5 1/2" Long Coarse Thread Grade 8	Ea.		5.89	11.78
2	CS1-6	Cap Screw 5/8" Dia. X 6" Long	Ea.		6.10	12.20
4	SN58	Stop Nut 5/8" Dia. (Stover Type GRADE C)	Ea.		2.67	10.68
8	FW58	Flat Washer 5/8"	Ea.		1.72	13.76

CHECK ☒ PAID CASH ☐ C.C. ☐

Total

17747 JUN 03 2022

R & H SPRING & TRUCK REPAIR, INC.



SPRING & TRUCK REPAIR

Your Auto, Truck & Trailer
Suspension and Alignment Specialists

Fax: (732) 681-5887
Phone: (732) 681-9000
4806 W. Hurley Pond Rd.
Wall, NJ 07719
www.mhspring.com

SERVICE INVOICE

Date

Invoice #


5/23/2022

67896

Visit us at WWW.RNHSpring.com

BILL TO

Delisa Demolition Inc.
101 Commerce Dr.
Tinton Falls, NJ 07753
Phone: (732) 988-2525
Joe cell (908)415-1456



State Tax ID/Phone#

ST4/223634028
mtsi@optonline.net
OK
Fax: (732) 988-8333

CC Code

Vehicle/Trailer/Parts

P.O. No.

Payment Terms

Mileage

Due Date

Plate #

Vehicle #

2004 Mack RD690S

29,129

5/23/2022

88

Qty	Item	Description	U/M	List	Rate	Amount
25	CS381	Cap Screw 3/8 X 1 Grade 8	Ea.		1.32	34.32
25	HN38	Hex Nut, Non Lock, 3/8" X 16 TPI	Ea.		0.28	7.28
25	LW	Lock Washers			0.38	9.88
52	FW38	Flat washer 3/8	Ea.		1.09	56.68
4	CS78412	Cap Screw 7/8" Dia. X 4 1/2" Long Coarse Thread Grade 8	Ea.		11.36	45.44
2	TMR557	MACK TORQUE ROD 20"	Ea.		197.31	394.62
1	TMR559	Mack Torque Rod	Ea.		215.91	215.91
1	Torq	Torque Rod Part#TMRN950			140.55556	140.56
32	LHeavy	Heavy Equipment Labor Per Hour (15K GVW Plus)			150.00	4,800.00T
		Subtotal before fees				13,223.46
		NOTE: Left rear wheel seal leaking				
		Sales Tax			6.625%	318.00

Total

\$13,541.46

CUSTOMER: Please read and sign; **HAVE INSTALLED U-BOLTS & LUGS RETIGHTENED WITHIN 30 DAYS.** R&H is committed to customer satisfaction. If you are not satisfied let us know immediately. Undersigned is 100% Satisfied with Repairs/Parts/Service & price listed above

CUSTOMER SIGNATURE _____